

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG23000990/ANP3E2
Date: 04/05/2023**REFERENCE**

Insured/Claimant:	WYNNE CHIA XIE YONGNI	Policy No:	7210105647
Date of Loss:	16/01/2023	Nature of Claim:	OD
		Claim No:	1752860848SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB6251B	Engine No:	DGK005710
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZFY1M2085923
Reg. Date:	31/08/2021 (Man. Year: 2021)	Odometer:	11741 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$225,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,852.00	5,122.00	5,730.00	52.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	1,602.00	3,150.00	66.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,604.00	6,724.00	8,880.00	56.91
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	15,104.00	6,224.00	8,880.00	58.79
+ GST 8.00/8.00% (S\$)	1,208.32	497.92	710.40	58.79
Nett Amount (S\$)	16,312.32	6,721.92	9,590.40	58.79

INSPECTION

Date of Assignment:	01/02/2023		
Date Inspected:	31/01/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BUMPER - UPPER / LOWER	Deformed	3,600.00 FS	*2,880.00 FS
2	1		*REAR BUMPER LOWER TRIM - RH	Not Necessary	136.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	382.00 FS	*305.60 FS
4	1		*REAR BUMPER TOW EYE COVER - RH	Not Necessary	56.00 FS	*- FS
5	1		*REAR BUMPER DIFFUSER	Not Necessary	398.00 FS	*- FS
6	1		*REAR BUMPER TRIM - RH	Cut	290.00 FS	*232.00 FS
7	1		*REAR BUMPER TRIM - CENTER	Not Necessary	198.00 FS	*- FS
8	1		*REAR BUMPER LIGHT - RH	Cracked	826.00 FS	*660.40 FS
9	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	491.00 FS	*- FS
10	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	129.00 FS	*- FS
11	1		*REAR AERIAL KEY ACCESS	Not Necessary	123.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,104.00 FS	*- FS
13	2		*REAR BUMPER IMPACT BAR GASKET - LH / RH	Not Necessary	7.00 FS	*- FS
14	1		*REAR BUMPER HOLDING STRAP	Not Necessary	201.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	100.00 FS	*- FS
16	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	543.00 FS	*- FS
17	4		*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
18	1		*SET REAR BUMPER WIRING	Not Necessary	551.00 FS	*- FS
19	2		*REAR WHEEL COVER - LH / RH	Necessary	1,306.00 FS	*1,044.00 FS
20	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,852.00	5,122.00
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,752.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >