

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23000999/UPA3Q2**Date:** 11/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPCM1000000125
Claimant Vehicle No :	SJA6060M	Insured Vehicle No :	XD2353M
Date of Loss:	21/01/2023	Nature of Claim:	TP
		Claim No:	202332004890

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA6060M	Engine No:	A082I107
Make & Model:	MINI COOPER S, 1.6 ABS D/AB GAS/D TC (A)	Chassis No:	WMWMF72090TV02488
Reg. Date:	11/06/2008 (Man. Year: 2007)	Odometer:	255048 km
Colour:	Yellow		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,073.65	8,548.65	11,525.00	57.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	1,690.00	2,830.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,593.65	10,238.65	14,355.00	58.37
Approved Total (Overridden) (S\$)		8,100.00		
Nett Amount (S\$)	24,593.65	8,100.00	16,493.65	67.06
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		57.75		
Nett Liability (S\$)		8,517.75		
Global Sum Settlement (S\$)		8,500.00		

INSPECTION

Date of Assignment:	31/01/2023	Profi Automotive (KB)
Date Inspected:	01/02/2023 Inspected At:	10 KAKI BUKIT ROAD 2, #01-05 FIRST EAST CENTRE
Estimated Period of Repair:	5.0 days	Singapore 417868

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	M1-COUPE	MINI COOPER S 1.6 ABS D/AB GAS/D TC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA6060M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented / Bent	1,130.00 FL	*980.00 FL
2	1		*FRONT FENDER INNER SHIELD RH	Twisted	195.00 FL	*195.00 FL
3	1		*FRONT FENDER OUTER TRIM RH	Distorted	438.00 FL	*366.00 FL
4	1		*FRONT FENDER SIDE GARNISH RH	No such part	339.00 FL	*- FL
5	1		*FRONT SIGNAL LAMP RH	Scratched	380.00 FL	*190.00 FL
6	1		*FRONT DOOR PANEL RH	Dented / Bent	2,319.00 FL	*1,458.00 FL
7	1		*FRONT DOOR UPPER HINGE RH	Not Necessary	108.00 FL	*- FL
8	1		*FRONT DOOR LOWER HINGE RH	Not Necessary	108.00 FL	*- FL
9	1		*FRONT DOOR CHECKER RH	Not Necessary	126.00 FL	*- FL
10	1		*FRONT DOOR LOCK ASSEMBLY	Damaged / Malfunction	1,205.00 FL	*490.00 FL
11	1		*FRONT DOOR REGULATOR RH	Not Necessary	1,343.00 FL	*- FL
12	1		*FRONT DOOR INNER TRIM RH	Deformed / Torn	913.00 FL	*688.00 FL
13	1		*FRONT WING MIRROR RH	Broken	1,585.00 FL	*905.00 FL
14	1		*FRONT HEADLAMP RH	Scratched	3,990.00 FL	*1,520.00 FL
15	1		*FRONT HEADLAMP CHROME RH	Scratched	329.00 FL	*155.00 FL
16	1		*FRONT RIM RH	Warped	1,180.00 FL	*600.00 FL
17	1		*FRONT RIM CAP	Not Necessary	319.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM RH	Bent	899.00 FL	*620.00 FL
19	1		*FRONT KNUCKLE ARM BEARING RH	Damaged	330.00 FL	*305.00 FL
20	1		*FRONT LOWER ARM RH	Bent	559.00 FL	*495.00 FL
21	1		*FRONT SHOCK ABSORBER RH	Not Necessary	1,522.00 FL	*- FL
22	1		*SIDE SKIRT RH	Not Necessary	950.00 FL	*- FL
23	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*30.00 FS
24	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
25	1		*BOTTLE BRAKE FLUID	Not Necessary	100.00 FS	*- FS
26	1		*FRONT TYRE	Serviceable	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,087.00	8,997.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,013.35	448.35
Total Parts (\$\$)	20,073.65	8,548.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	200.00	20.00
2	DIAGNOSE CHECK ,CLEAR FAULT CODE	New	600.00	0.00
3	COMPUTERISED WHEEL ALIGNMENT	New	200.00	100.00
4	FLUSH AND TOP-UP BRAKE FLUID	New	120.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD DOOR TO NEW	New	250.00	60.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
8	APPLY ANTI-RUST	New	150.00	30.00
9	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	600.00	380.00
Gross Labour Cost (\$\$)			4,520.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >