



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 1352L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FORK INNER TUBES (CONSISTENT)	NOT NECESSARY	280.00	-
2	FORK OUTER TUBES (CONSISTENT)	NOT NECESSARY	290.00	-
1	FORK UNDER BRACKER (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	42.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	38.00	-
1	FRONT SIGNAL (O/S) (CONSISTENT)	CRACKED	130.00	60.00
1	SIDE MIRROR (O/S) (CONSISTENT)	CUT	96.00	68.00
1	HANDLE-BAR (CONSISTENT)	SERVICEABLE	80.00	-
1	HANDLE BAR ENDS (CONSISTENT)	SCRATCHED	95.00	30.00
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	50.00	-
1	HEADLAMP (CONSISTENT)	SCRATCHED	160.00	160.00
1	FRONT FOOTREST BRACKET (CONSISTENT)	BENT	55.00	55.00
1	FRONT FOOTREST RUBBERS (CONSISTENT)	TORN	56.00	56.00
1	BRAKE PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	42.00	-
2	REAR FOOTREST (CONSISTENT)	NOT NECESSARY	76.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	130.00	-
1	REAR TAILLAMP (CONSISTENT)	BROKEN	88.00	88.00
1	REAR FENDER (CONSISTENT)	BROKEN	68.00	68.00
1	REAR SPORT RIM (CONSISTENT)	WARPED	380.00	380.00
1	REAR RIM SHAFT (CONSISTENT)	BENT	68.00	50.00
1	REAR SWING ARM (CONSISTENT)	NOT NECESSARY	450.00	-
1	REAR ABSORBER (CONSISTENT)	NOT NECESSARY	320.00	-
1	EXHAUST ASSY (CONSISTENT)	BENT	428.00	428.00
1	EXHAUST PROTECTOR (CONSISTENT)	BENT	98.00	98.00
1	BASKET (CONSISTENT)	TO REPAIR SEE LABOUR	58.00	-
1	FAIRING ASSY (CONSISTENT)	CRACKED	485.00	485.00
	LESS 10% DISCOUNT		-452.80	-202.60
			4,075.20	1,823.40

Report Ref No. CS/HSB23001007/Uqp3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	REAR BENT	38.00	10.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE BEARING (SN) (CONSISTENT)	NOT NECESSARY	85.00	-
1	REAR BOX (SN) (CONSISTENT)	CUT	200.00	180.00
1	REAR BOX BRACKET (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	100.00	-
1	SET STICKER (SN) (CONSISTENT)	NECESSARY	90.00	60.00
			599.00	250.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING (LOD) S\$70.00 (NPA).	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF BRAKE PEDAL, BASKET AND REAR BOX BRACKET.		420.00	300.00
			980.00	300.00
	GRAND TOTAL		5,654.20	2,373.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/HSB23001007/Uqp3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.