



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 6883Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH DOOR GLASS OUTER MOULDING (WCP)	CUT	78.00	78.00
2	TAILLAMPS @\$405.00 (WCP)	CRACKED	810.00	810.00
1	REAR BOOT LOGO (WCP)	NECESSARY	35.00	35.00
1	REAR BOOT EMBLEM (E200) (WCP)	NECESSARY	90.00	90.00
1	BONNET LOGO (WCP)	NECESSARY	56.00	56.00
	COST PLUS 15%		160.35	160.35
			1,229.35	1,229.35
	<u>LABOUR</u>			
	REMOVE & REFIX ALL NECESSARY PARTS TO ENABLE TO PUTTY & RESPRAY PAINTING,KNOCK & REPAIR REAR RH FENDER AND REALIGN THE SAME.		600.00	500.00
	PUTTY & RESPRAY ON BONNET,FRT BOTH FENDERS,FRT BUMPER,FRT & REAR LH DOORS,FRT & REAR RH DOORS,REAR BUMPER,REAR BOTH FENDERS,BONNET,RH SIDE MIRROR,FUEL TANK DOOR PANEL,TOP ROOF.		2,800.00	2,400.00
			3,400.00	2,900.00
	GRAND TOTAL		4,629.35	4,129.35

RECOMMENDED COST OF REPAIRS			4,129.35
LESS EXCESS			-500.00
NETT LIABILITY			3,629.35

Report Ref No. CS/LPC23001012/Kcp3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.