

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|----------------|---------|-----------------------|--|
| | LONPAC INSURAN | ICE BHD | | Ref: | CS/LPC23001012/Kcp3m4 | |
| | 300 BEACH ROAD #17-04/07 THE CO | NCOURSESINGAPORE 199555 | | Date: | 27/07/2023 | |
| | | | | Code: | LPC2 | |
| 1. | I. Policy Particulars :- OWN DAMAGE | | | | | |
| | Insured Veh. | | Veh. Inspected | | SFB 6883Y | |
| | Policy No. | Z22VP05031963 | Coverage (\$) | | 0.00 | |
| | Claim No. | 22/23/23/VP05/026893 | Excess (\$) | | 500.00 | |
| | Assign From | GERALD POH | Assign Date | | 01/02/2023 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | MERCEDES E200 (A) | c.c | | 1991 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2016 | |
| | Chassis No. | WDD2130422A027556 | Colour | | METALLIC BLACK | |
| | Odometer | 113843 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 245/45 R18 | PIRELLI | | 7 mm | |
| | L/H Front Tyre | 245/45 R18 | PIRELLI | | 7 mm | |
| | R/H Rear Tyre | 245/45 R18 | PIRELLI | | 7 mm | |
| | L/H Rear Tyre | 245/45 R18 | PIRELLI | | 7 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE FOUND DAMAGED AT THE VEHICLE PAINT WORK AT THE TIME OF INSPECTION. THE CAUSE OF DAMAGED DUE TO VANDALISM. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 21/01/2023 | Inspection Dat | е | 01/02/2023 | |
| | Survey held at | CHENG HOE MOTOR PL | | | | |
| | | BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761 | | | | |
| 5a. | a. Remarks | | | | | |
| | A)THE MARKET VALUE IS S\$118,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | | 10 Work | king Days | |
| | | | | | | |