

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB23001015/KPA3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447_02
Claimant Vehicle No :	SMG9474R	Insured Vehicle No :	SLL598L
Date of Loss:	28/01/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9474R	Engine No:	G4FGJU040295
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU809830
Reg. Date:	07/01/2019 (Man. Year: 2018)	Odometer:	82028 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,819.20	3,602.88	9,216.32	71.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,740.00	1,510.00	46.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,069.20	5,342.88	10,726.32	66.75
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	16,069.20	4,000.00	12,069.20	75.11
+ GST 8.00/8.00% (S\$)	1,285.54	320.00	965.54	75.11
Nett Amount (S\$)	17,354.74	4,320.00	13,034.74	75.11
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		4,946.75		

INSPECTION

Date of Assignment:	31/01/2023		
Date Inspected:	31/01/2023	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG9474R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	983.00 FL	*498.80 FL
2	1		*REAR BUMPER LOWER	Bent	467.00 FL	*340.60 FL
3	1		*REAR BUMPER LOWER SPOILER	Bent	414.00 FL	*414.00 FL
4	2		*REAR BUMPER REFLECTOR	Cracked	630.00 FL	*403.00 FL
5	2		*REAR BUMPER SPLASH GUARD	Cracked (1 PCS ONLY)	190.00 FL	*95.00 FL
6	1		*REAR BUMPER IMPACT ABSORBER	No such part	166.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Cracked	559.00 FL	*294.80 FL
8	2		*REAR BUMPER SIDE SUPPORT	Distorted	178.00 FL	*178.00 FL
9	2		*REAR SIDE RETAINER	Serviceable	130.00 FL	*- FL
10	2		*REAR FENDER	Repair	1,720.00 FL	*- FL
11	2		*REAR FENDER COWLING	Serviceable	392.00 FL	*- FL
12	1		*TAILLAMP	N/S Cut	1,122.00 FL	*561.00 FL
13	2		*TAILLAMP WEATHERSTRIP SPONGE	Serviceable	32.00 FL	*- FL
14	1		*END PANEL	Bent	532.00 FL	*485.90 FL
15	1		*END PANEL TOP GARNISH	Mtg Distorted	177.00 FL	*142.30 FL
16	1		*SPARE WHEEL TOP BOARD	Serviceable	196.00 FL	*- FL
17	1		*REAR FLOOR PANEL	Repair	884.00 FL	*- FL
18	1		*BOOTLID	Repair	1,785.00 FL	*- FL
19	1		*BOOTLID INNER TRIM	Serviceable	149.00 FL	*- FL
20	1		*BOOTLID LOCK	Dented	224.00 FL	*166.70 FL
21	1		*BOOTLID LOCK STRIKER	Repair	56.00 FL	*- FL
22	1		*BOOTLID AVANTE EMBLEM	Necessary	53.00 FL	*53.00 FL
23	1		*BOOTLID HYUNDAI LOGO	Necessary	69.00 FL	*69.00 FL
24	2		*BOOTLID LAMP	Serviceable	1,358.00 FL	*- FL
25	2		*SIDE AIR VENT	Serviceable	96.00 FL	*- FL
26	1		*EXHAUST ASSY	Repair	689.00 FL	*- FL
27	2		*EXHAUST MOUNTING	Serviceable	70.00 FL	*- FL
28	2		*EXHAUST BRACKET	Repair	88.00 FL	*- FL
29	1		*EXHAUST HEATSHIELD	Serviceable	118.00 FL	*- FL
30	2		*REAR LICENCE PLATE LAMP	Serviceable	286.00 FL	*- FL
31	1		*REAR BUMPER TOW COVER	Missing	39.00 FL	*39.00 FL
32	2		*REAR FENDER INNER TRIM	Serviceable	662.00 FL	*- FL
33	12		*REAR BUMPER CLIPS	Necessary	54.00 FS	*54.00 FS
34	8		*REAR FENDER COWLING CLIPS	Not Necessary	36.00 FS	*- FS
35	8		*TAILLAMP CLIPS	Not Necessary	36.00 FS	*- FS
36	2		*REVERSE SENSOR (FACTORY ORIGINAL)	Shorted	572.00 FS	*454.00 FS
37	1		*END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
38	6		*END PANEL TOP GARNISH CLIPS	Necessary	27.00 FS	*27.00 FS
39	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
40	8		*BOOTLID INNER TRIM CLIPS	Not Necessary	36.00 FS	*- FS
41	16		*REAR FENDER INNER TRIM CLIPS	Not Necessary	72.00 FS	*- FS
42	1		*REAR LICENCE PLATE & FRAME	Bent	55.00 FS	*45.00 FS
43	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)15,722.004,351.10

- List Item Discount on L Items 20.00/20.00% (\$\$)2,902.80748.22

Report was unsubmitted during this print-out.

5/25/23, 2:43 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,819.20 3,602.88
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,600.00	800.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS	New	50.00	20.00
3	TO REMOVE AND REFIT INTERIOR UPHOLSTERY ,INNER TRIM ,INNER GARNISH ,MOULDINGS TO FACILITATE THE REPAIR	New	100.00	60.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,400.00	800.00
5	TO RUST PROOF ACCIDENT AFFECTED PORTIONS	New	100.00	60.00
Gross Labour Cost (\$\$)			3,250.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >