

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001016/UNP3E2**Date:** 09/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00124352203
<b>Claimant Vehicle No :</b>	SMD3552D	<b>Insured Vehicle No :</b>	SJU3756D
Date of Loss:	20/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200675/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMD3552D</b>	Engine No:	3A92UHA8442
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH002409
Reg. Date:	16/08/2018 (Man. Year: 2018)	Odometer:	66573 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,460.23	2,031.55	3,428.68	62.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,220.00	1,030.00	45.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,710.23</b>	<b>3,251.55</b>	<b>4,458.68</b>	<b>57.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	7,710.23	2,600.00	5,110.23	66.28
<b>+ GST 8.00/8.00% (S\$)</b>	616.82	208.00	408.82	66.28
<b>Nett Amount (S\$)</b>	<b>8,327.05</b>	<b>2,808.00</b>	<b>5,519.05</b>	<b>66.28</b>

INSPECTION

Date of Assignment:	31/01/2023	
Date Inspected:	31/01/2023	Inspected At: Convergence Automotive Pte Ltd (HQ) 39 Woodlands Close, MEGA@Woodlands #01-24 Singapore 737856
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
<b>Parts:</b>	143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMD3552D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	788.00 FN	*751.00 FN
2	2		*REAR BUMPER SIDE RETAINER	Bent	124.00 FN	*56.00 FN
3	1		*REAR BUMPER REINFORCEMENT	No such part	576.00 FN	*- FN
4	1		*REAR BUMPER LOWER COWING	Not fitted	288.00 FN	*- FN
5	2		*REAR BUMPER TOP BRACKET	Not Necessary	140.00 FN	*- FN
6	1		*LOWER SKIRTING	Cracked	1,008.50 FN	*1,008.50 FN
7	1		*END PANEL	Repair	532.00 FN	*- FN
8	1		*END PANEL TOP GARNISH	Twisted	164.00 FN	*164.00 FN
9	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	488.00 FN	*- FN
10	1		*REAR END PANEL BUZZLE SENSOR	Not Necessary	108.00 FN	*- FN
11	1		*REAR END PANEL INNER AIR VENT	Not Necessary	127.00 FN	*- FN
12	1		*REAR END PANEL INNER AIR VENT GARNISH	Not Necessary	136.00 FN	*- FN
13	1		*REAR EXHAUST PIPE	Not Necessary	845.20 FN	*- FN
14	1		*REAR EXHAUST HANGER	Not Necessary	65.00 FN	*- FN
15	1		*REAR EXHAUST GASKET	Not Necessary	55.00 FN	*- FN
16	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
17	1		*SET REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
19	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>6,004.70</b>	<b>2,229.50</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	544.47	197.95
<b>Total Parts (S\$)</b>	<b>5,460.23</b>	<b>2,031.55</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT EXHAUST PIPE	New	150.00	0.00
2	TO REMOVE AND REFIT REVERSE CAMERA & SENSORS	New	100.00	50.00
3	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	100.00	20.00
4	TO APPLY UNDERCOATING & RUST PROOFING	New	100.00	0.00
5	PANEL BEATING	New	1,000.00	550.00
6	SPRAY PAINTING	New	800.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,250.00</b>	<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >