

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001018/KQP3Q2**Date:** 15/03/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG22016951
Claimant Vehicle No :	SFE6655Z	Insured Vehicle No :	SNH7675Z
Date of Loss:	22/01/2023	Nature of Claim:	TP
		Claim No:	CDMPG23000255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFE6655Z	Engine No:	2ZR1948936
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	ZVW400025098
Reg. Date:	14/07/2017 (Man. Year: 2017)	Odometer:	496297 km
Colour:	Metallic Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Arivo 9 mm	Rear Left Side:	Arivo 9 mm
Front Right Side:	Arivo 9 mm	Rear Right Side:	Arivo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,561.12	3,957.71	4,603.41	53.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,400.00	1,300.00	48.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,261.12	5,357.71	5,903.41	52.42
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	11,261.12	4,250.00	7,011.12	62.26
+ GST 8.00/8.00% (S\$)	900.89	340.00	560.89	62.26
Nett Amount (S\$)	12,162.01	4,590.00	7,572.01	62.26

INSPECTION

Date of Assignment:	31/01/2023	
Date Inspected:	01/02/2023	Inspected At: Blk 176 Sin Ming Drive #04-09 Sin Ming Autocare
Estimated Period of Repair:	5.0 days	Repairer: Hui Yang Motor Pte Ltd (HQ)

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFE6655Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,218.45 FL	*1,218.45 FL
2	1		*REAR TAILGATE OUTER GARNISH	Serviceable	371.25 FL	*- FL
3	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	61.10 FL	*- FL
4	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	63.90 FL	*63.90 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	61.10 FL	*61.10 FL
6	1		*SET REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	182.28 FL	*- FL
7	1		*REAR TAILGATE INNER LOCK	Dented	374.45 FL	*374.45 FL
8	1		*REAR TAILGATE INNER RUBBER	Serviceable	381.90 FL	*- FL
9	1		*REAR TAILGATE INNER GARNISH	Mtg Distorted	781.90 FL	*781.90 FL
10	1		*REAR TAILLAMP	O/S Cracked	1,363.80 FL	*681.90 FL
11	1		*REAR TAILLAMP LOWER BRACKET	O/S Distorted	265.00 FL	*132.50 FL
12	1		*REAR BUMPER	Buckled	981.90 FL	*823.00 FL
13	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	264.90 FL	*132.45 FL
14	1		*REAR BUMPER LH REFLECTOR	Serviceable	181.25 FL	*- FL
15	1		*REAR END PANEL	Bent	781.10 FL	*687.30 FL
16	1		*REAR END PANEL INNER GARNISH	Serviceable	374.85 FL	*- FL
17	2		*REAR FENDER INNER GARNISH	Serviceable	1,563.00 FL	*- FL
18	1		*REAR FLOOR PANEL	Repair	981.50 FL	*- FL
19	1		*REAR FLOOR PANEL TOP TRIM	Serviceable	681.20 FL	*- FL
20	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
21	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	11,294.83 5,196.95
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,733.71 1,239.24
					Total Parts (S\$)	8,561.12 3,957.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TUFFKOTE	New	100.00	60.00
3	WIRING	New	80.00	20.00
4	SPRAY PAINTING	New	1,200.00	600.00
5	LABOUR CHARGES	New	1,200.00	600.00
Gross Labour Cost (S\$)			2,700.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >