

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001021/UNP3Q2**Date:** 24/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00003982200		
Claimant Vehicle No :	SMP6352G	Insured Vehicle No :	SLS3384E		
Date of Loss:	28/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200763/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6352G	Engine No:	L13B3934325
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GK33419834
Reg. Date:	04/10/2019 (Man. Year: 2019)	Odometer:	34902 km
Colour:	White		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,015.56	1,171.60	7,843.96	87.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,650.00	1,460.00	46.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,125.56	2,821.60	9,303.96	76.73
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	12,125.56	2,200.00	9,925.56	81.86

INSPECTION

Date of Assignment:	17/02/2023		
Date Inspected:	01/02/2023	Inspected At:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2023)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6352G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,127.50 FL	*- FL
2	1		*TAILGATE LOCK	Not Necessary	189.60 FL	*- FL
3	1		*TAILGATE INNER TRIM	Not Necessary	342.50 FL	*- FL
4	1		*TAILGATE BADGE -FIT	Not Necessary	72.00 FL	*- FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	213.20 FL	*- FL
6	1		*TAILGATE OUTER GARNISH LOGO	Not Necessary	78.20 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Not Necessary	186.60 FL	*- FL
8	2		*TAILGATE TAIL LIGHT	Not Necessary	590.20 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Not Necessary	235.00 FL	*- FL
10	1		*TAILLAMP ASSY L-R	N/S Cut / O/S Not Necessary	1,164.60 FL	*365.00 FL
11	1		*REAR BUMPER	Dented	675.20 FL	*492.70 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Bent	99.20 FL	*25.00 FL
13	1		*REAR BUMPER LOWER MOULDING	Cut	368.20 FL	*108.00 FL
14	1		*REAR BUMPER SIDE GARNISH	N/S Cut / O/S Not Necessary	149.20 FL	*74.60 FL
15	1		*REAR END PANEL	Bent / Twisted	662.30 FL	*349.20 FL
16	1		*REAR END PANEL GARNISH	Not Necessary	242.30 FL	*- FL
17	2		*TAILLAMP BASE PANEL -LH	Repair	324.60 FL	*- FL
18	1		*SMART BUZZER -REVERSE	Not Necessary	124.00 FL	*- FL
19	1		*SPARE TYRE PANEL BOARD	Not Necessary	394.20 FL	*- FL
20	1		*SPARE TYRE INSULATOR /SPONGE	Not Necessary	249.60 FL	*- FL
21	1		*SHOCK ABSORBER L/H	Not Necessary	600.00 FL	*- FL
22	1		*WHEEL BEARING L/H	Not Necessary	500.00 FL	*- FL
23	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
24	3		*REAR WINDSCREEN DAMPER	Not Necessary	35.00 FS	*- FS
25	1		*REAR LICENSE PLATE	Not Necessary	50.00 FS	*- FS
26	1		*SET TAILGATE INNER TRIM BOARD CLIP	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*40.00 FS
28	2		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
29	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	260.00 FS	*- FS
30	1		*SPORT RIM	Not Necessary	600.00 FS	*- FS
31	1		*TIRE	Not Necessary	500.00 FS	*- FS
32	1		*REAR VIEW CAM	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,733.20	1,454.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,717.64	282.90
Total Parts (\$)	9,015.56	1,171.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS	New	1,200.00	750.00
2	TO RESPRAY REPLACED AND AFFECTED PANELS	New	1,300.00	800.00
3	TO CARRY OUT ANTI RUST TREATMENT	New	120.00	30.00
4	TO REMOVE AND TRANSFER REAR WINDSCREEN	New	150.00	0.00
5	TO CHECK WIRING FOR PROPER FUNCTION	New	80.00	20.00
6	TO INSTALL REAR BUMPER SENSOR	New	80.00	50.00
7	TO REMOVE AND REPLACE EXHAUST MUFFLER	New	100.00	0.00
8	TO PROVIDE TOWING SERVICE	New	80.00	0.00
Gross Labour Cost (S\$)			3,110.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >