

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23001027/KQP3E2**Date:** 17/02/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002564406
Claimant Vehicle No :	SJG8311U	Insured Vehicle No :	SMQ6622Y
Date of Loss:	08/01/2023	Nature of Claim:	TP
		Claim No:	299306

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG8311U	Engine No:	3ZZ4779875
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106112803
Reg. Date:	17/07/2008 (Man. Year: 2008)	Odometer:	195642 km
Colour:	Metallic Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,212.42	3,912.02	4,300.40	52.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,500.00	1,900.00	55.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,612.42	5,412.02	6,200.40	53.39
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	11,612.42	4,200.00	7,412.42	63.83
+ GST 8.00/8.00% (S\$)	928.99	336.00	592.99	63.83
Nett Amount (S\$)	12,541.41	4,536.00	8,005.41	63.83

INSPECTION

Date of Assignment:	01/02/2023	
Date Inspected:	01/02/2023 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG8311U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	556.00 FL	*556.00 FL
2	14		*FRONT BUMPER CLIPS	Necessary	53.20 FL	*53.20 FL
3	1		*FRONT BUMPER CORNER RETAINER RH	Distorted	73.20 FL	*73.20 FL
4	1		*FRONT BUMPER EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*HEADLAMP RH	Cut	1,007.00 FL	*781.20 FL
6	1		*WIPER TANK	Serviceable	165.00 FL	*- FL
7	1		*WIPER TANK MOTOR	Serviceable	235.00 FL	*- FL
8	1		*FRONT FENDER RH	Bent	845.00 FL	*651.20 FL
9	1		*FRONT FENDER BADGE VVTI	Necessary	45.00 FL	*45.00 FL
10	1		*FRONT FENDER SHIELD	Serviceable	161.00 FL	*- FL
11	10		*FRONT FENDER SHIELD CLIPS	Not Necessary	38.00 FL	*- FL
12	1		*FRONT DOOR RH	Bent / Warped	1,236.00 FL	*1,102.80 FL
13	1		*FRONT DOOR STICKER	Necessary	70.00 FL	*70.00 FL
14	1		*FRONT DOOR PROTECTOR	Necessary	357.00 FL	*357.00 FL
15	1		*FRONT DOOR PROTECTOR MOULDING	Necessary	225.00 FL	*225.00 FL
16	1		*FRONT DOOR WING MIRROR	Serviceable	1,045.00 FL	*- FL
17	1		*FRONT DOOR WING MIRROR SIGNAL LAMP	Cracked	90.00 FL	*90.00 FL
18	1		*FRONT DOOR TOP HINGE	Repair	145.00 FL	*- FL
19	1		*FRONT DOOR LOWER HINGE	Repair	145.00 FL	*- FL
20	1		*FRONT DOOR PROTECTOR	Repeated	357.00 FL	*- FL
21	1		*FRONT DOOR PROTECTOR MOULDING	Repeated	225.00 FL	*- FL
22	1		*ROCKER PANEL SKIRT	Cracked	862.00 FL	*765.10 FL
23	10		*ROCKER PANEL SKIRT CLIPS	Necessary	38.00 FL	*38.00 FL
24	1		*FRONT WHEEL BEARING	Not Necessary	589.00 FL	*- FL
25	1		*FRONT SHOCK ABSORBER	Serviceable	380.60 FL	*- FL
26	1		*FRONT KNUCKLE ARM	Serviceable	440.40 FL	*- FL
27	1		*FRONT LOWER ARM	Serviceable	459.30 FL	*- FL
28	1		*REAR BUMPER	Serviceable	579.00 FL	*- FL
29	14		*REAR BUMPER CLIPS	Not Necessary	53.20 FL	*- FL
30	1		*FRONT WHEEL RIM RH	Dented	300.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,849.90	5,132.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,637.48	1,220.68
Total Parts (\$\$)	8,212.42	3,912.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK, FOCUS HEADLAMP	New	40.00	20.00
2	TO DISMANTLE / REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR	New	250.00	0.00
3	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	TO CONDUCT HIGH SPEED BALANCING	New	80.00	20.00
5	TO PROVIDE TRANSPORTATION (TOWING)	New	100.00	50.00
6	TO REPAIR REAR RIM RH (DISMANTLE/SPRAY/REFIT)	New	150.00	0.00
7	LABOUR CHARGE - PANEL BEATING, REPAIRING OF FRONT FENDER INNER PANEL, DOOR PILLAR, ROCKER PANEL & PART REPLACEMENT	New	700.00	550.00
8	TO SPRAY PAINT AFFECTED AREAS(F BUMPER, F FENDER, F DOOR, RR DOOR, PROTECTORS*2, SIDE SKIRT, ROCKER PANEL, RR FENDER, RR BUMPER)	New	2,000.00	800.00
Gross Labour Cost (\$)			3,400.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >