



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFG 1616J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT	TO REPAIR SEE LABOUR	966.50	-
1	REAR BUMPER ASSY	DISTORTED	733.00	733.00
2	REAR BUMPER REFLECTOR @\$90.00	NOT NECESSARY	180.00	-
1	REAR BUMPER TOW COVER	NOT FITTED	56.00	-
1	REAR LOCKING MECHANISM	NOT NECESSARY	196.20	-
1	REAR LOCKING PIN	NOT NECESSARY	63.00	-
1	END PANEL	BADLY DENTED	763.60	763.60
1	END PANEL TOP GARNISH	TWISTED	265.30	265.30
1	REINFORCEMENT BEAM	NO SUCH PARTS	537.40	-
2	REINFORCEMENT HOLDER @\$186.04	NOT NECESSARY	372.08	-
1	REINFORCEMENT SPONGE	TORN	132.10	132.10
1	REAR BOOT WEATHERSTRIP	TWISTED	289.10	289.10
	LESS 25% DISCOUNT		-	-545.78
			4,554.28	1,637.32
<b><u>SPECIAL NETT ITEMS</u></b>				
1	LICENSE PLATE (SN)	NOT NECESSARY	80.00	-
1	LICENSE PLATE BRACKET (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	1,000.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	1,000.00	-
1	SET CLIPS (BUMPER) (SN)	NECESSARY	50.00	50.00
			2,180.00	250.00
<b><u>LABOUR</u></b>				
	LABOUR FOR CHECKING ON WIRING.		150.00	20.00
	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING CUTTING OFF ,WELDING,KNOCKING ,REPAIRING ,STRAIGHTENING ,RESHAPE OF REAR CHASSIS MEMBER ,FLOOR BOARD PANEL & ADJUSTMENT OF REAR SIDE BUMPER ,BOOT ,HINGES DAMPER ,TAIL LAMPS ,BOOT LAMP,REVERSE CAM & SENSOR.INCLUSIVE OF THE REPAIR OF REAR BOOT .		2,950.00	1,000.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON REPAIRED & REPLACE PANELS.		350.00	40.00
	SPRAYPAINTING & PUTTY OF REAR BUMPER ,REAR BOOT LID ,HINGES ,END PANEL ,SPARE WHEEL FLOOR & REVERSE SENSOR .		1,900.00	900.00
			5,350.00	1,960.00
<b>GRAND TOTAL</b>			<b>12,084.28</b>	<b>3,847.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,000.00</b>

Report Ref No. CS/AGI23001029/Uqp3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.