

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001030/TNP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00076502201
Claimant Vehicle No :	SGQ7661Z	Insured Vehicle No :	SGY4554C
Date of Loss:	20/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200771/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGQ7661Z	Engine No:	4G18HX0189
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Chassis No:	JMYSNCS3A7U005492
Reg. Date:	24/01/2007 (Man. Year: 2006)	Odometer:	235537 km
Colour:	Black		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,562.00	679.50	1,882.50	73.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	400.00	150.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,112.00	1,079.50	2,032.50	65.31
Approved Total (Overridden) (S\$)		850.00		
(S\$)	3,112.00	850.00	2,262.00	72.69
+ GST 8.00/8.00% (S\$)	248.96	68.00	180.96	72.69
Nett Amount (S\$)	3,360.96	918.00	2,442.96	72.69

INSPECTION

Date of Assignment:	22/02/2023		
Date Inspected:	02/02/2023	Inspected At:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ7661Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	1,438.00 F	*695.00 FL
2	1		*FRT BUMPER SIDE RETAINER RH	Deformed	88.00 F	*60.00 FL
3	1		*FRT HEADLAMP ASSY RH	Not Necessary	1,036.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	2,562.00 755.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 75.50
					Total Parts (S\$)	2,562.00 679.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	250.00	200.00
2	TO PUTTY & RESPRAY PAINTING ON BUMPER	New	300.00	200.00
Gross Labour Cost (S\$)			550.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >