

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001033/AWP3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00220022200		
Claimant Vehicle No :	CB7753T	Insured Vehicle No :	SML8869R		
Date of Loss:	19/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200548/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7753T	Engine No:	4D34K85567
Make & Model:	MITSUBISHI BE639JRMHDEA, 3.9 D (M)	Chassis No:	BE639JD00312
Reg. Date:	18/07/2006 (Man. Year: 2006)	Odometer:	769094 km
Colour:	White		
Engine Capacity:	3908 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R12.5	Rear Tyre Size:	215/75 R12.5
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,392.26	3,749.55	12,642.71	77.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	2,410.00	3,800.00	61.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,602.26	6,159.55	16,442.71	72.75
Approved Total (Overridden) (\$\$)		4,900.00		
Nett Amount (\$\$)	22,602.26	4,900.00	17,702.26	78.32

INSPECTION

Date of Assignment:	01/02/2023	
Date Inspected:	28/03/2023 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 May 2023)	
Parts:	N/A	MITSUBISHI BE639JRMHDEA 3.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB7753T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,170.00 FL	*1,750.00 FL
2	1		*FRONT BUMPER SIDE BRACKET	N/S Damaged	138.00 FL	*69.00 FL
3	1		*HEADLAMP LH	Cracked	864.80 FL	*864.80 FL
4	1		*HEADLAMP TOP GARNISH LH	Not Necessary	165.00 FL	*- FL
5	1		*FRONT SIDE PANE LH	Dented	1,450.00 FL	*1,190.00 FL
6	1		*FRONT SIDE PANEL LAMP LH	Cut	175.00 FL	*175.00 FL
7	1		*FRONT SIGNAL LAMP LH	Cracked	255.60 FL	*255.60 FL
8	1		*SIDE PANEL LH	Repair	6,834.00 FL	*- FL
9	1		*SIDE PANEL LAMP LH	Cut	175.00 FL	*175.00 FL
10	1		*DOOR STEP PANEL LH	Repair	380.00 FL	*- FL
11	1		*DOOR STEP PANEL PROTECTOR LH	Dented	180.00 FL	*180.00 FL
12	1		*FRONT DOOR LH	Repair	2,534.00 FL	*- FL
13	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	350.00 FL	*- FL
14	1		*FRONT WHEEL COWLING LH	Deformed	220.00 FL	*220.00 FL
15	1		*SET FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
16	1		*STICKER (SCHOOL BUS)	Necessary	40.00 FS	*30.00 FS
17	2		*FRONT PANEL BLACK STICKER	Not Necessary	40.00 FS	*- FS
18	2		*SIDE PANEL BLACK STICKER	Not Necessary	80.00 FS	*- FS
19	2		*FRONT SIDE GLASS SEALANT	Necessary	160.00 FS	*60.00 FS
20	2		*FRONT SIDE GLASS INNER SHIELD	Not Necessary	160.00 FS	*- FS
21	3		*SIDE GLASS SEALANT	Not Necessary	240.00 FS	*- FS
22	3		*SIDE GLASS INNER SHIELD	Not Necessary	240.00 FS	*- FS
23	2		*FRONT DOOR GLASS WITH STRIP	Not Necessary	400.00 FS	*- FS
24	1		*FRONT TYRE LH	Not Necessary	680.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,981.40	4,969.40
- List Item Discount on L Items 10.00/25.00% (S\$)	1,589.14	1,219.85
Total Parts (S\$)	16,392.26	3,749.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	2,500.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,200.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX SIDE PANEL GLASS	New	750.00	0.00
6	REMOVE AND REFIX FRONT DOOR GLASS	New	200.00	0.00
7	TRANSFER FRONT DOOR MECHANISM	New	100.00	0.00
8	REMOVE & REINSTALL FRONT GLASS	New	250.00	100.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			6,210.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >