

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD INV No. AC2303948

300 BEACH ROAD INV Date 20/06/2023

#17-04/07 THE CONCOURSE Reference CC4/LPC23001037/Kpa3q2 SINGAPORE 199555

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SBR 8008H

Insured Veh. SJQ 9746P

Claim No. 22/23/23/VP05/026915

Policy No. Z21VP05029321

Accident Date 31/01/2023

Inspection Date 03/02/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD		Ref:	CC4/LPC23001037/Kpa3q2		
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	20/06/2023		
				Code:	LPC2		
1.		Policy Particulars	:- THIRD PARTY	CLAIN	1		
	Insured Veh.	SJQ 9746P	Veh. Inspected		SBR 8008H		
	Policy No.	Z21VP05029321	Coverage (\$)		0.00		
	Claim No.	22/23/23/VP05/026915	Excess (\$)		0.00		
	Assign From	GERALD	Assign Date		01/02/2023		
2.		Vehicle Partic	culars & Conditi	on			
	Make & Model	TOYOTA HARRIER (A)	c.c		1986		
	Engine No.	HIDDEN	Year of Reg.		2014		
	Chassis No.	ZSU600022502	Colour		METALLIC PEARL WHITE		
	Odometer	162834 KM	Steering		IN ORDER		
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM		
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make		Balance		
	R/H Front Tyre	235/55 R18	PIRELLI		6 mm		
	L/H Front Tyre	235/55 R18	PIRELLI		6 mm		
	R/H Rear Tyre	235/55 R18	CONTINENTAL		5 mm		
	L/H Rear Tyre	235/55 R18	CONTINENTAL		5 mm		
4.		Description	on of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT PORTION.				
	DAMAGES SEE DETAILS.						
5.		General	Information				
	Accident Date	31/01/2023	Inspection Dat	е	03/02/2023		
	Survey held at	TSR AUTOMOTIVE PTE LTD	•				
		160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722					
5a.		Re	emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days						
	<u> </u>						



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBR 8008H

1 BONNE	ACEMENT OF PARTS ET (NPA)			
1 BONNE	ET (NPA)			
		TO REPAIR SEE LABOUR	-	-
1 FRONT	T BUMPER	BUCKLED / CRACKED	785.00	785.00
1 FRONT	Γ BUMPER RETAINERS (O/S)	DISTORTED	442.00	68.00
1 FRONT	T BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	620.00	-
1 FRONT	FBUMPER CENTER SPONGE	CRACKED	580.00	125.00
1 FRONT	TBUMPER SIDE SPONGE LH	SERVICEABLE	298.00	-
1 FRONT	F BUMPER CENTER BRACKET	TO REPAIR SEE LABOUR	350.00	-
3 FRONT	T BUMPER SENSORS	SHORTED (1 PCS ONLY)	660.00	284.00
1 SET FR	RONT BUMPER SENSOR CABLE	SERVICEABLE	385.00	-
1 FRONT	Γ BUMPER LOWER GRILLE	CRACKED	428.50	284.00
1 FRONT	Γ BUMPER LOWER GARNISH	SERVICEABLE	519.60	-
1 FRONT	T TOW COVER RH	SERVICEABLE	220.00	-
1 FRONT	Γ CENTER GRILLE	CRACKED	785.90	598.50
2 HEADL	AMPS	O/S MTG CRACKED	5,712.00	2,856.00
2 HEADL	LAMP LOWER BRACKETS	TO REPAIR SEE LABOUR	440.00	-
1 FRONT	T SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
2 FRONT	Γ FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
LESS 2	25% DISCOUNT		-3,056.50	-1,250.13
			9,169.50	3,750.37
SPECI	IAL NETT ITEMS			
10 FRONT	Γ BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
	RONT NO PLATE WITH FRAME (SN)	DENTED	60.00	45.00
			105.00	90.00

Report Ref No. CC4/LPC23001037/Kpa3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,400.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES TO REPLACE ,REPAIR ,REMOVE REFIX ON FRONT ACCIDENT AFFECTED AREA .INCLUSIVE OF THE REPAIR OF BONNET,FRONT BUMPER REINFORCEMENT ,FRONT BUMPER CENTER BRACKET,HEADLAMP LOWER BRACKETS ,FRONT SUPPORT PANEL AND FRONT FENDER .		800.00	300.00
	TO DO ANTI RUST .	NOT NECESSARY	90.00	-
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA .		1,000.00	220.00
	TO CHECK WIRING SYSTEM ,FORCUS HRADLAMPS .		120.00	20.00
	TO DIGNOSE ,DELETE FAULT CODE,RESET DECODE AFTER REPAIR .	NOT NECESSARY	280.00	-
			2,290.00	540.00
	GRAND TOTAL		11,564.50	4,380.37

Report Ref No. CC4/LPC23001037/Kpa3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBR 8008H

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBR 8008H

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBR 8008H

RE-INSPECTION



