

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 62504489 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2301-068-TG
DATE : 31-Jan-2023
VEHICLE REG. NO. : **SMU4468T**
VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A)
REG : 14 Aug 20

TO China Taiping

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1		\$ -
2	Front Bumper Retainer RH LH	2		\$ -
3	Front Bumper Lower Moulding RH - 86571P	1		\$ -
4	Front License Plate Garnish	1		\$ -
5	Front Bumper Under Lip Assy - 86590E	1		\$ -
6	Front Reinforcement	1		\$ -
7	Front Stiffener 86571L	1		\$ -
8	Front Sponge	1		\$ -
9	Front Grille (with Emblem)	1		\$ -
10	Front Grille Bracket RH LH 86553B	2		\$ -
11	Support Panel Top Cover 86360M	1		\$ -
12	Headlamp RH LH	2		\$ -
13	Headlamp Bracket RH LH	2		\$ -
14	Support Panel	1		\$ -
15	Rear Bumper	1		\$ -
16	Rear Bumper Lower	1		\$ -
17	Rear Bumper Retainer RH LH	2		\$ -
18	Rear license Plate Garnish	1		\$ -
19	Rear Reflector RH LH 92405F	2		\$ -
20	Rear Bumper Cover RH 86690A	1		\$ -
21	Rear Reinforcement 86631D	1		\$ -
22	Rear Reinforcement Stay RH LH 86641A	2		\$ -
23	Rear key Antenna 95420H	1		\$ -
24	Rear Bumper Guard RH 86352W	1		\$ -
25	End Panel	1		\$ -
26	End Panel Garnish	1		\$ -
27	Spare Tyre Sink	1		\$ -
28	Bootlid	1		\$ -
29	Bootlid Hinge RH LH	2		\$ -
30	Bootlid Emblem	1		\$ -
31	Bootlid Emblem S	1		\$ -
32	Bootlid Emblem Avante	1		\$ -

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 62504489 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2301-068-TG
DATE : 31-Jan-2023
VEHICLE REG. NO. : **SMU4468T**
VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A)
REG : 14 Aug 20

TO China Taiping

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
33	Bootlid Inner Trim	1		\$ -
34	Bootlid Hinge Torsion RH LH	2		\$ -
35	Bootlid Locky Assy 81260B	1		\$ -
36	Bootlid Latch Assy 81230	1		\$ -
37	Bootlid Striker 81210B	1		\$ -
38	Boot Weatherseal	1		\$ -
39	Bootlid Lamp RH	1		\$ -
40	Rear Fender Complete RH 70200A	1		\$ -
41	Tail Lamp Panel RH 71585	1		\$ -
42	Tail Lamp RH	1		\$ -
43	Tail Lamp Clip	1		\$ -
44	Rear Fendershield RH Front	1		\$ -
45	Rear Fendershield RH Back	1		\$ -
46	Rear Fendershield RH Mudguard	1		\$ -
47	Exhaust Muffler	1		\$ -
48	Exhaust Mounting Bush	1		\$ -
Total Spare Parts				\$ -
	<u>SPECIAL NETT</u>			
49	Front License Plate with Casing	1	\$ 40.00	\$ 40.00
50	Rear License Plate with Casing	1	\$ 40.00	\$ 40.00
51	Front Bumper Clips	10	\$ 3.00	\$ 30.00
52	Rear Bumper Clips	10	\$ 3.00	\$ 30.00
53	Rear Fendershield Clips	10	\$ 3.00	\$ 30.00
54	Bootlid Inner Trim Clips	10	\$ 3.00	\$ 30.00
55	New Parts Edge Sealant (Bootlid)	1	\$ 60.00	\$ 60.00
56	Reverse Sensors	1	\$ 280.00	\$ 280.00
Total Special Nett				\$ 540.00
	<u>LABOUR</u>			
57	Remove, Refit, Replace and Repair Affected Area	1	\$ 2,200.00	\$ 2,200.00
58	Spray painting (Front Bumper, Rear Bumper, Rear Fender LH, Bootlid, End Panel, Tyre Sink)	1	\$ 1,500.00	\$ 1,500.00
59	Remove & Replace Reverse Sensor	1	\$ 80.00	\$ 80.00
60	Wheel Alignment	1	\$ 70.00	\$ 70.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 62504489 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2301-068-TG

DATE : 31-Jan-2023

VEHICLE REG. NO. : **SMU4468T**

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A)

REG : 14 Aug 20

TO China Taiping

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
61	Anti Rust Proofing	3	\$ 40.00	\$ 120.00
62	Run OBD Diagnosis and Clear Faults	1	\$ 150.00	\$ 150.00
63	Check/Rectify Wiring	1	\$ 20.00	\$ 20.00
Total Labour				\$ 4,140.00
Amount Before Excess				\$ 4,680.00
Add GST @ 8%				374.40
Total Amount Payable				\$ 5,054.40

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts/labour which may be required after work has been started. Worn or damaged parts are discovered which may not be evident on first inspection. Because of this,