

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23001043/SWP3Q2**Date:** 26/06/2023**REFERENCE**

Insured/Claimant:	SYNERGY LEASING PTE LTD	Policy No:	SP2001256008
Date of Loss:	19/01/2023	Nature of Claim:	OD Claim No: 202332004765

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2064S		
Make & Model:	TOYOTA HIACE, 2.0 (M)	Engine No:	1KD2662759
Reg. Date:	28/06/2017 (Man. Year: 2016)	Chassis No:	KDH2010209650
Colour:	Black	Odometer:	109552 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$44,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,125.00	2,563.00	1,562.00	37.87
Miscellaneous Items	50.00	30.00	20.00	40.00
Labour	1,000.00	600.00	400.00	40.00
Paintwork Labour	1,400.00	800.00	600.00	42.86
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,575.00	3,993.00	2,582.00	39.27
Approved Total (Overridden) (S\$)		2,800.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	6,575.00	800.00	5,775.00	87.83
+ GST 8.00/8.00% (S\$)	526.00	64.00	462.00	87.83
Nett Amount (S\$)	7,101.00	864.00	6,237.00	87.83

INSPECTION

Date of Assignment:	31/01/2023	Present Location:	Century Motors Pte Ltd (HQ)
Date Inspected:	02/02/2023	Inspected At:	6 MARSILING LANE S739145
Estimated Period of Repair:	5.0 days	Repairer:	Century Motors Pte Ltd (HQ)

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2023)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG2064S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	280.00 F	*280.00 F
2	1		*FRONT FENDER LH (WCP)	Dented	90.00 F	*90.00 F
3	1		*FRONT FENDER MIRROR LH (WCP)	Dented	85.00 F	*85.00 F
4	1		*FRONT BUMPER (WCP)	Dented	230.00 F	*230.00 F
5	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Cracked	60.00 F	*60.00 F
6	1		*FRONT DOOR LH (WCP)	Dented	660.00 F	*660.00 F
7	1		*SIDE MIRROR LH (WCP)	Cracked	360.00 F	*360.00 F
8	1		*STEP PANEL LH (WCP)	Cut	80.00 F	*80.00 F
9	1		*B PILLAR OUTER PANEL LH (WCP) (NPA)	Repair	-	*- F
10	1		*REAR SLIDING DOOR LH (WCP)	Repair	700.00 F	*- F
11	1		*REAR FENDER LH (WCP)	Repair	720.00 F	*- F
12	1		*HEADLAMP LH (WCP)	Cracked	350.00 F	*350.00 F
13	1		*REAR TAILLAMP LH (WCP)	Cracked	135.00 F	*135.00 F
						F=Franchise part.
					Sub Total (\$\$)	3,750.00 2,330.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	375.00 233.00
					Total Parts (\$\$)	4,125.00 2,563.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	30.00
Sub Total (\$\$)			50.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	LABOUR FOR SPRAY PAINTING	New	1,400.00	800.00
Labour Items				
2	LABOUR FOR PANEL BEATING	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,400.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >