

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23001046/AQP3M4**Date:** 05/04/2023**REFERENCE**

Insured/Claimant:	HENG JENNY	Policy No:	1800074527	
Date of Loss:	13/01/2023	Nature of Claim:	OD	Claim No: 9891744981SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCE35M		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX035687
Reg. Date:	04/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF9J2157396
Colour:	Blue	Odometer:	39408 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,083.00	3,704.00	13,379.00	78.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,272.00	2,672.00	3,600.00	57.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,355.00	6,376.00	16,979.00	72.70
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	22,855.00	5,876.00	16,979.00	74.29
+ GST 8.00/8.00% (\$\$)	1,828.40	470.08	1,358.32	74.29
Nett Amount (\$\$)	24,683.40	6,346.08	18,337.32	74.29

INSPECTION

Date of Assignment:	02/02/2023	
Date Inspected:	01/02/2023	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER - LH	Deformed	1,536.00 FS	*1,228.80 FS
2	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	45.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	133.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Deformed	900.00 FS	*720.00 FS
5	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	614.00 FS	*- FS
6	1		*FRONT BUMPER LOWER PANEL	Not Necessary	260.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	691.00 FS	*552.80 FS
8	1		*FRONT OUTER GRILLE BAFFLE - LH	Not Necessary	109.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	46.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	152.00 FS	*- FS
11	1		*AIR CONDITONER STICKER	Not Necessary	24.00 FS	*- FS
12	1		*CAUTION SIGN STICKER	Not Necessary	17.00 FS	*- FS
13	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	272.00 FS	*- FS
14	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
15	1		*HEADLIGHT MOUNTING - LH	Not Necessary	140.00 FS	*- FS
16	1		*HEADLIGHT MOUNTING BRACE - LH LOWER	Not Necessary	67.00 FS	*- FS
17	1		*HEADLIGHT MOUNTING SUPPORT - LH	Not Necessary	63.00 FS	*- FS
18	1		*HEADLIGHT - LH	Not Necessary	9,226.00 FS	*- FS
19	1		*LIFT CYLINDER - LH	Not Necessary	162.00 FS	*- FS
20	1		*LIFT CYLINDER HOSE	Not Necessary	150.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	326.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER DUST COVER - LH	Not Necessary	44.00 FS	*- FS
23	1		*FRONT WHEEL SPOILER	Not Necessary	191.00 FS	*- FS
24	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,504.00 FS	*1,202.40 FS
25	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
					Total Parts (\$\$)	17,083.00 3,704.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,272.00	2,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >