

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG23001047/AQP3E2**Date:** 13/02/2023**REFERENCE**

Insured/Claimant:	ANGELA CHAN RUO JUN	Policy No:	1900130169	
Date of Loss:	13/01/2023	Nature of Claim:	OD	Claim No: 4496301431SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLR4875D</b>		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZ508633
Reg. Date:	16/08/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V4J1005325
Colour:	Black	Odometer:	126462 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,154.00	2,734.00	7,420.00	73.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,372.00	1,522.00	6,850.00	81.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,526.00</b>	<b>4,256.00</b>	<b>14,270.00</b>	<b>77.03</b>
<b>+ GST 8.00/8.00% (S\$)</b>	1,482.08	340.48	1,141.60	77.03
<b>Nett Amount (S\$)</b>	<b>20,008.08</b>	<b>4,596.48</b>	<b>15,411.60</b>	<b>77.03</b>

**INSPECTION**

Date of Assignment:	02/02/2023		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	01/02/2023	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,180.00 NETT)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,455.00 FS	*2,455.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	213.00 FS	*- FS
3	1		*REAR WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	45.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	38.00 FS	*- FS
5	1		*REAR BUMPER LOCKING MECHANISM	Not Necessary	36.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Cut	279.00 FS	*279.00 FS
7	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	49.00 FS	*- FS
8	1		*REAR OUTER TAIL LIGHT - RH	Not Necessary	1,030.00 FS	*- FS
9	1		*REAR OUTER TAIL LIGHT TRIM - RH	Not Necessary	36.00 FS	*- FS
10	1		*REAR INNER TAIL LIGHT - RH	Not Necessary	1,030.00 FS	*- FS
11	1		*REAR INNER TAIL LIGHT TRIM - RH	Not Necessary	36.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	* Check	680.00 FS	*- FS
13	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	67.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	79.00 FS	*- FS
15	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	543.00 FS	*- FS
16	4		*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
17	1		*SET REAR BUMPER WIRING	Not Necessary	578.00 FS	*- FS
18	1		*REAR CROSS PANEL	Not Necessary	402.00 FS	*- FS
19	1		*REAR CROSS PANEL REINFORCEMENT	Not Necessary	925.00 FS	*- FS
20	2		*REAR CROSS PANEL CONNECTING PLATE - LH / RH	Not Necessary	342.00 FS	*- FS
21	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
22	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
23	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
24	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
25	1		*SUNDRIES	* Check	500.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>10,154.00      2,734.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	500.00
4	TO RESPRAY REAR BUMPER, REAR END PANELLING AND SPARE WHEEL HOUSING	New	3,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>8,372.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >