

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG 23001049/4pa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ397Eat Workshop m/s 14's Bld

of _____

Insured: GBJ1079R

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 52k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: LIA @ 11730

Vehicle: IN / OUT

Veh No: GBJ397EYr Regn: 05/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CMMake: Nissan NV200c.c. 1461Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 170302

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM 2020173564Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/70R14R: Austone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Aplus.

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/01/23D.O.I. 2/2/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction Rep 9k.Rear door glass LH hit by 07 side mirror scene photo can see10/1/23 L/S @ 4300 in front Susan.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Ref Date:

Ref No:

Vehicle No:

Model / Make:

30-01-2023

GBJ399Z230128

GBJ399Z

Nissan

NV200 1.5 MT

not Added
2/2/23
4/5 4300
6 Days

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper	\$ 632.70	1	\$ 632.70	N	✓
2		Bumper Clips 1set	\$ 40.00	1	\$ 40.00	SN	✓ s/n
3		Bumper Sponge	\$ 182.50	1	\$ 182.50	N	✓
4		End Panel Outer	\$ 411.80	1	\$ 411.80	N	✓
5		End Panel Inner	\$ 455.20	1	\$ 455.20	N	X
6		End Panel Top Garnish	\$ 108.60	1	\$ 108.60	N	X
7	1set	Bumper Reverse Sensor	\$ 220.00	1	\$ 220.00	SN	200 s/n
8	Rear Rh	Bumper Reflector Rh	\$ 45.00	1	\$ 45.00	N	✓
9		Tailgate	\$ 1,102.30	1	\$ 1,102.30	N	✓
10		Tailgate Lower Lock	\$ 115.00	1	\$ 115.00	N	✓
11		Tailgate Lower Hinge	\$ 102.80	1	\$ 102.80	N	X
12		Tailgate Inner Trim	\$ 166.20	1	\$ 166.20	N	✓
13		Tail Lamp	\$ 319.70	1	\$ 319.70	N	✓
14		Tailgate "PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	10 s/n
15		Windscreen Glass Sealant	\$ 80.00	1	\$ 80.00	SN	40 s/n
16	Rear Lh	Tailgate	\$ 1,545.40	1	\$ 1,545.40		X
17		Tailgate Windscreen Glass	\$ 580.00	1	\$ 580.00		✓
18		Windscreen Glass Sealant	\$ 80.00	1	\$ 80.00	SN	40 s/n
19		Tailgate "NV 200" Emblem	\$ 163.50	1	\$ 163.50	N	✓
20		Tailgate "NISSAN" Logo Motif	\$ 155.90	1	\$ 155.90	N	X
21		Tailgate "70 KM/H" Sticker	\$ 15.00	1	\$ 15.00	SN	10 s/n
22		Remove & reinstall RH & LH Tailgate Glass to facilitate repairs			\$ 240.00	-	200
23		To check all wiring & electrical component for proper function			\$ 60.00	-	20
24		Remove and refix rear Rh tailgate tailgate components & mechanism			\$ 120.00	-	60
25		Remove and refix rear bumper reverse sensor			\$ 80.00		40
26		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 800.00		720
27		To putty & spray painting & including touch up paint on accident affected areas			\$ 900.00		600
28		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 100.00		60

Total Parts & Labour of estimate for damaged vehicle

\$ 8,836.60

Total amount in Lumpsum Basis for repaired vehicle

SDL

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Liu's Bro Auto Engrg Wks

9-371870
102
3346.88
340
1700
5868