

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001054/RQP3Q2**Date:** 27/03/2023REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00016772200

Claimant Vehicle No : SLZ7396H **Insured Vehicle No :** SME6337J

Date of Loss: 25/01/2023 Nature of Claim: TP Claim No: SNM23D200592/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ7396H**

Make & Model: VOLKSWAGEN TIGUAN, 1.4 TSI (A) Engine No: CZE546042

Reg. Date: 14/05/2018 (Man. Year: 2017) Chassis No: WVGZZZ5NZJW848831

Colour: White Odometer: 61244 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,269.48	10,453.12	816.36	7.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,690.00	8,570.00	4,120.00	32.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,959.48	19,023.12	4,936.36	20.60
+ GST 8.00/8.00% (S\$)	1,916.76	1,521.85	394.91	20.60
Nett Amount (S\$)	25,876.24	20,544.97	5,331.27	20.60

INSPECTION

Date of Assignment: 01/02/2023

Date Inspected: 02/02/2023 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts: M1-SUV	VOLKSWAGEN TIGUAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLZ7396H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER LHS FENDER	Repair	816.36 FS	*- FS
2	1		*WHEEL COVER SATIN BLACK LHS FENDER WHEEL ARCH	Scratched	244.63 FS	*244.63 FS
3	8		*GROMMET	Necessary	15.04 FS	*15.04 FS
4	1		*DOOR LHS FRT DOOR	Bent	2,254.08 FS	*2,254.08 FS
5	1		*DOOR SEAL OUTER BLACK	Necessary	267.94 FS	*267.94 FS
6	1		*ALU-LAMIN INSULATION DOOR INSULATOR	Necessary	43.66 FS	*43.66 FS
7	2		*BOLT WITH POLYGON SOCKET	Necessary	11.42 FS	*11.42 FS
8	2		*FILL,HD,SCREW	Necessary	6.24 FS	*6.24 FS
9	3		*RIVET	Necessary	3.81 FS	*3.81 FS
10	1		*FELT STRIP	Necessary	24.17 FS	*24.17 FS
11	1		*COVER FOR DOOR SATIN BLAC LHS FRT DOOR LOWER PROTECTOR	Deformed	343.25 FS	*343.25 FS
12	8		*GROMMET	Necessary	15.04 FS	*15.04 FS
13	1		*DOOR LHS REAR DOOR	Bent	3,065.64 FS	*3,065.64 FS
14	1		*DOOR SEAL OUTER BLACK	Necessary	248.04 FS	*248.04 FS
15	1		*ALU-LARNIN ,INSULATION DOOR INSULATOR	Necessary	43.66 FS	*43.66 FS
16	2		*BOLT WITH POLYGON SOCKET	Necessary	11.42 FS	*11.42 FS
17	2		*FILL .HD SCREW	Necessary	6.24 FS	*6.24 FS
18	2		*CLIP	Necessary	3.12 FS	*3.12 FS
19	3		*RIVET	Necessary	3.81 FS	*3.81 FS
20	1		*COVER FOR DOOR SATIN BLAC LHS REAR DOOR LOWER PROTECTOR	Scratched	500.95 FS	*500.95 FS
21	8		*GROMMET	Necessary	15.04 FS	*15.04 FS
22	1		*WHEEL COVER SATIN BLACK LHR FENDER WHEEL ARCH	Scratched	426.03 FS	*426.03 FS
23	8		*GROMMET	Necessary	15.04 FS	*15.04 FS
24	1		*STICKER WITH PICTOGRAM FO B-PILLAR AIR BAG STICKER	Necessary	24.97 FS	*24.97 FS
25	1		*ALLOY WHEEL DIAMOND SILVE	Scratched	2,855.89 FS	*2,855.89 FS
26	1		*RUBBER VALVE	Necessary	3.99 FS	*3.99 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 11,269.48 10,453.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	B&P WHEEL ALIGNMENT	New	360.00	360.00
4	R&R RIM & BALANCE	New	50.00	50.00
5	LABOUR	New	5,040.00	3,360.00
6	SPRAY PAINT	New	4,800.00	3,200.00
7	TRANSFER DOOR MECHANISM	New	1,680.00	840.00
			Gross Labour Cost (S\$)	12,690.00
				8,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >