

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001060/RVP3Q2**Date:** 05/04/2023**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00134702200

**Claimant Vehicle  
No :** SKM8228J**Insured Vehicle  
No :** SNF5491K

Date of Loss: 24/01/2023

Nature of Claim: TP

Claim  
No: SNM23D200656/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKM8228J**

Make &amp; Model: JAGUAR F-PACE, 2.0 P RWD (A)

Engine No: 200128Y0607PT204

Reg. Date: 21/01/2021 (Man. Year: 2020)

Chassis No: SADCA2AX9LA647758

Colour: Black

Odometer: 28503 km

Engine Capacity: 1997 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 255/55 R19

Rear Tyre Size: 255/55 R19

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,787.40	9,022.77	2,764.63	23.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,101.00	7,201.00	2,900.00	28.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,888.40</b>	<b>16,223.77</b>	<b>5,664.63</b>	<b>25.88</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,751.07</b>	<b>1,297.90</b>	<b>453.17</b>	<b>25.88</b>
<b>Nett Amount (S\$)</b>	<b>23,639.47</b>	<b>17,521.67</b>	<b>6,117.80</b>	<b>25.88</b>

**INSPECTION**

Date of Assignment: 01/02/2023

Date Inspected: 08/02/2023 Inspected At:

45 Leng Kee Road  
Repairer: Wearnes Automotive Pte Ltd (Alexandra Road)

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	144	JAGUAR F-PACE 2.0 P RWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM8228J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*D PRIMER GLASS & P	Necessary	46.90 FS	*42.21 FS
2	2		*SEALANT WINDSCREEN	Necessary	385.80 FS	*347.22 FS
3	1		*GLASS -BACKLI	Necessary	1,479.90 FS	*1,331.91 FS
4	1		*PANEL -TRUNK LID	Cracked	2,940.30 FS	*2,646.27 FS
5	1		*BADGE F-PACE	Necessary	233.80 FS	*210.42 FS
6	1		*BADGE -HALF LEAPER	Necessary	203.60 FS	*183.24 FS
7	1		*BADGE 25T AWD	Necessary	173.00 FS	*155.70 FS
8	1		*COVER -BUMPER REAR	Deformed	2,275.00 FS	*2,047.50 FS
9	1		*COVER -TWNG HK OPNNG	Not Necessary	38.80 FS	*- FS
10	1		*PANEL VALANCE	Deformed	299.00 FS	*269.10 FS
11	1		*MOUNTING -BRACKET	Not Necessary	272.30 FS	*- FS
12	1		*BRACKET -BUMPER LH	Not Necessary	142.60 FS	*- FS
13	1		*BRACKET -BUMPER RH	Not Necessary	142.60 FS	*- FS
14	1		*MOUNTING -BRACKET LH	Not Necessary	187.80 FS	*- FS
15	1		*MOUNTING -BRACKET RH	Not Necessary	162.10 FS	*- FS
16	1		*MOLDING LH	Not Necessary	148.30 FS	*- FS
17	1		*MOLDING RH	Not Necessary	148.30 FS	*- FS
18	1		*RH SILENCER -EXH RR A	Bent	1,921.90 FS	*1,729.71 FS
19	1		*CLAMP -EXHAUST	Necessary	66.10 FS	*59.49 FS
20	1		*HEATSHIELD RH	Not Necessary	85.30 FS	*- FS
21	1		*HEATSHIELD RH	Not Necessary	71.70 FS	*- FS
22	1		*LAMP -FOG RH	Not Necessary	362.30 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	11,787.40	9,022.77
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE TAILGATE ,REAR BUMP LOWER BUMPER ,BRACKETS ,CLIPS ,ETC	New	3,000.00	2,000.00
2	TO BLEND AND SPRAY PAINT ON TAILGATE ,REAR BUMPER ,ETC	New	2,700.00	1,800.00
3	TO TRANSFER TAILGATE MECHANISM	New	500.00	500.00
4	TO REPLACE REAR WINDSCREEN	New	1,000.00	1,000.00
5	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	280.00	280.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
7	TO REPLACE EXHAUST SYSTEM	New	2,000.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,101.00</b>	<b>7,201.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >