

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23001064/DQP3M4**Date:** 12/06/2023**REFERENCE**

Insured/Claimant: ZHANG CHUNHUA Policy No: SP2001188008-01
Date of Loss: 27/01/2023 Nature of Claim: OD Claim No: 202332004905

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ3447X**
Make & Model: TOYOTA LEXUS, 2.5 ES250 EXECUTIVE S/R (A) Engine No: 2ARF582223
Reg. Date: 30/04/2018 (Man. Year: 2018) Chassis No: JTHBJ1GGX02108451
Colour: Silver Odometer: 57600 km
Engine Capacity: 2494 cc
Market Value/New Car Price: S\$138,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,923.60	5,776.10	2,147.50	27.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,120.00	430.00	27.74
Paintwork Labour	1,400.00	1,000.00	400.00	28.57
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,873.60	7,896.10	2,977.50	27.38
Approved Total (Overridden) (S\$)		6,300.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	10,273.60	5,700.00	4,573.60	44.52
+ GST 8.00/8.00% (S\$)	821.89	456.00	365.89	44.52
Nett Amount (S\$)	11,095.49	6,156.00	4,939.49	44.52

INSPECTION

Date of Assignment: 01/02/2023 Present Location: Success United Pte Ltd (HQ)
Date Inspected: 03/02/2023 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921
Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2023)
Parts:	143	TOYOTA LEXUS 2.5 ES250 EXECUTIVE S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ3447X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH (WCP)	Dented	750.00 F	*750.00 F
2	1		*FRT DOOR WING MIRROR ASSY LH (WCP)	Not Necessary	680.00 F	*- F
3	1		*FRT DOOR GLASS OUTER CHROME TRIM MOULDING LH (WCP)	Bent	280.00 F	*280.00 F
4	1		*FRT DOOR OUTER HANDLE LH (WCP)	Cut	250.00 F	*250.00 F
5	1		*FRT DOOR WEATHERSTRIP LH (WCP)	Necessary	165.00 F	*165.00 F
6	1		*FRT DOOR MECHANISM LOCK LH (WCP)	Not Necessary	220.00 F	*- F
7	1		*FRT DOOR LH REAR DOOR LH INSTEAD OF FRT DOOR LH (WCP)	Dented	780.00 F	*780.00 F
8	2		*FRT DOOR HINGE (TOP/LOWER) LH (WCP)	Bent	96.00 F	*96.00 F
9	1		*FRT DOOR CENTRE CHECKER LH (WCP)	Serviceable	65.00 F	*- F
10	1		*REAR DOOR WEATHERSTRIP LH (WCP)	Necessary	155.00 F	*155.00 F
11	1		*REAR DOOR FRONT RUBBER MOULDING LH (WCP)	Cut	80.00 F	*80.00 F
12	1		*REAR DOOR MECHANISM LOCK LH (WCP)	Bent	220.00 F	*220.00 F
13	1		*REAR DOOR SPEAKER LH (WCP)	Mtg Cracked	485.00 F	*485.00 F
14	1		*REAR DOOR GLASS LH (WCP)	Cut	230.00 F	*230.00 F
15	1		*REAR DOOR GLASS OUTER CHROME TRIM LH (TOP) (WCP)	Bent	150.00 F	*150.00 F
16	1		*REAR DOOR GLASS OUTER CHROME TRIM LH (LOWER) (WCP)	Bent	130.00 F	*130.00 F
17	1		*REAR DOOR OUTER HANDLE LH (WCP)	Cut	240.00 F	*240.00 F
18	1		*REAR DOOR GLASS REGULATOR GEAR UNIT ASSY LH (WCP)	Serviceable	485.00 F	*- F
19	1		*REAR DOOR GLASS REGULATOR GEAR MOTOR LH (WCP)	Not Necessary	380.00 F	*- F
20	1		*SIDE ROCKER SKIRT LH (WCP)	Cut	380.00 F	*380.00 F
21	1		*SIDE ROCKER PANEL LH (WCP)	Dented	580.00 F	*580.00 F
22	1		*SIDE ROCKER PANEL STEP TRIM GARNISH LH (WCP)	Bent	280.00 F	*280.00 F
23	1		*FRT FENDER INNER LINER LH (WCP)	Not Necessary	95.00 F	*- F
24	1		*FRT FENDER INNER LINER CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,206.00	5,251.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	717.60	525.10
Total Parts (\$\$)	7,923.60	5,776.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	To putty and respray painting on frt bumper, fender LH, frt door LH, door pillar LH, rear door LH, side rocker panel, side rocker skirt LH, rear fender LH.	New	1,400.00	1,000.00
Labour Items				
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	1,200.00	1,000.00
3	To remove, rearrange electrical wirings, check lighting.	New	100.00	0.00
4	To remove, replace door parts, transfer glass, gear & components.	New	250.00	120.00
Gross Labour Cost (\$\$)			2,950.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >