

ASS. REC. BY:

REF:

CS6/AIS 23001064/29p3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: P/P % • 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ 3447 X Yr Regn: April / 2018

Type: M:Car / M:Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus ES250 C.C. 2494Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 57600 T/Radio: Insured / Std / NI / NAEng/No: 2ARF 582223C/No: JT+BJ1G6X02108451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / VRim or

Tyre Size: F: 215/55 R17R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 27/01/2023 D.O.I. 03/02/2023Survey held at Desk Top Survey

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Allianz</u>
	<u>No second hand part.</u>
	<u>MV 138k</u>
	<u>LTA 51.7k</u>
	<u>HL 86.3k</u>

07/06/23 fringe 2/3 6,300/- with 7 days of pay
(red 4573.60, 42%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 71) 07/06/2023☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Report Format :

MEP-00Lump Sum / I.B.I. (\$) 6300

Success United Pte Ltd (Co.Reg.No:200402570G)2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SU230025
Policy No:	SP2001188008-01	Date of Loss:	27/01/2023
Vehicle Reg. No.:	SLZ3447X	Driveable?	
Driver Age/Info:	51 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	ZHANG CHUNHUA	Contact No:	+6597501848
Driver:	ZHANG CHUNHUA		

Make/Model:	TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) EXECUTIVE (A)	Vehicle Reg. Date:	30/04/2018
Vehicle Colour:	SILVER	Chassis No:	JTHBJ1GGX02108451
Engine No:	2ARF582223		
Odometer:	57600 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Description of Accident/Loss	REFER TO POLICE REPORT. REPORT NO: T/20230128/2018.
Present Location:	SUCCESS UNITED PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	7,923.60
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	1,400.00
Towing	0.00
Calculated Gross Total (S\$)	10,873.60
- Excess (S\$)	600.00
(S\$)	10,273.60
+ GST 8.00% (S\$)	821.89
Nett Amount (S\$)	11,095.49

This claim is handled by: LAW YI TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jan 2023)

Parts: 143 TOYOTA LEXUS 2.5 ES250 4DR SEDAN (AUTO) EXECUTIVE E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Success United Pte Ltd/SLZ3447X/31/01/2023 18:36

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT DOOR LH <i>Renel</i>	0.00	0.00	*750.00 F	✓
2	1		*FRT DOOR WING MIRROR ASSY LH <i>HL</i>	0.00	0.00	*680.00 F	X
3	1		*FRT DOOR GLASS OUTER CHROME TRIM MOULDING LH <i>HL</i>	0.00	0.00	*280.00 F	✓
4	1		*FRT DOOR OUTER HANDLE LH <i>Cut</i>	0.00	0.00	*250.00 F	✓
5	1		*FRT DOOR WEATHERSTRIP LH <i>HL</i>	0.00	0.00	*165.00 F	✓
6	1		*FRT DOOR MECHANISM LOCK LH <i>HL</i>	0.00	0.00	*220.00 F	X
7	1	<i>Rear</i>	*FRT DOOR LH <i>Renel</i>	0.00	0.00	*780.00	✓
8	2		*FRT DOOR HINGE (TOP/LOWER) LH <i>HL</i>	0.00	0.00	*96.00 F	✓
9	1		*FRT DOOR CENTRE CHECKER LH <i>HL</i>	0.00	0.00	*65.00 F	X
10	1		*REAR DOOR WEATHERSTRIP LH <i>HL</i>	0.00	0.00	*155.00 F	✓
11	1		*REAR DOOR FRONT RUBBER MOULDING LH <i>Cut</i>	0.00	0.00	*80.00 F	✓
12	1		*REAR DOOR MECHANISM LOCK LH <i>HL</i>	0.00	0.00	*220.00 F	✓
13	1		*REAR DOOR SPEAKER LH <i>HL</i>	0.00	0.00	*485.00 F	✓
14	1		*REAR DOOR GLASS LH <i>Cut</i>	0.00	0.00	*230.00 F	✓
15	1		*REAR DOOR GLASS OUTER CHROME TRIM LH (TOP) <i>HL</i>	0.00	0.00	*150.00 F	✓
16	1		*REAR DOOR GLASS OUTER CHROME TRIM LH (LOWER) <i>HL</i>	0.00	0.00	*130.00 F	✓
17	1		*REAR DOOR OUTER HANDLE LH <i>Cut</i>	0.00	0.00	*240.00 F	✓
18	1		*REAR DOOR GLASS REGULATOR GEAR UNIT ASSY LH <i>HL</i>	0.00	0.00	*485.00 F	X
19	1		*REAR DOOR GLASS REGULATOR GEAR MOTOR LH <i>HL</i>	0.00	0.00	*380.00 F	X
20	1		*SIDE ROCKER SKIRT LH <i>Cut</i>	0.00	0.00	*380.00 F	✓
21	1		*SIDE ROCKER PANEL LH <i>HL</i>	0.00	0.00	*580.00 F	✓
22	1		*SIDE ROCKER PANEL STEP TRIM GARNISH LH <i>HL</i>	0.00	0.00	*280.00 F	✓
23	1		*FRT FENDER INNER LINER LH <i>HL</i>	0.00	0.00	*95.00 F	X
24	1		*FRT FENDER INNER LINER CLIPS <i>HL</i>	0	0.00	*30.00 FS	X

F=Franchise part, S=SpcNett.

Sub Total (\$\$) 7,206.00
+ Margin on L,N Items 10.00% (\$\$) 717.60

Total Parts (\$\$) 7,923.60

Success United Pte Ltd/SLZ3447X/31/01/2023 18:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

5251.10

Add 10% 5776.10 =

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To putty and respray painting on frt bumper, fender LH, frt door LH, door pillar LH, rear door LH, side rocker panel, side rocker skirt LH, rear fender LH.	New	1000/- 1,400.00
<u>Labour Items</u>			
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	1000/- 1,200.00
3	To remove, rearrange electrical wirings, check lighting.	New	44 100.00
4	To remove, replace door parts, transfer glass, gear & components.	New	120/- 250.00
Gross Labour Cost (\$\$)			2,950.00

Success United Pte Ltd/SLZ3447X/31/01/2023 18:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

03/02/2023 @ 1500hrs

Not Authored

?/Part. 7 days.

myan

2Kk And

7896.00

1/5 6,300/-

Excess to be advised.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: