

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23001066/SNP3E2**Date:** 22/06/2023**REFERENCE**

Insured/Claimant:	SYNERGY LEASING PTE LTD	Policy No:	SP2001256008
Date of Loss:	14/01/2023	Nature of Claim:	OD
		Claim No:	202332004707

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4141T	Engine No:	YD25066825B
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0031994
Reg. Date:	15/07/2020 (Man. Year: 2019)	Odometer:	50788 km
Colour:	Metallic Dark Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$59,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,626.00	9,971.50	654.50	6.16
Miscellaneous Items	95.00	60.00	35.00	36.84
Labour	1,000.00	800.00	200.00	20.00
Paintwork Labour	1,000.00	600.00	400.00	40.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,721.00	11,431.50	1,289.50	10.14
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	10,721.00	9,431.50	1,289.50	12.03
+ GST 8.00/8.00% (S\$)	857.68	754.52	103.16	12.03
Nett Amount (S\$)	11,578.68	10,186.02	1,392.66	12.03

INSPECTION

Date of Assignment:	01/02/2023		
Date Inspected:	01/02/2023	Inspected At:	6 Marsiling Lane S739145 Repairer: Century Motors Pte Ltd (HQ)
Estimated Period of Repair:	4.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jun 2023)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK4141T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL COMPLETE (WCP)	Buckled	780.00 F	*780.00 F
2	1		*FRONT GRILLE (WCP)	Cracked	420.00 F	*420.00 F
3	1		*FRONT GRILLE LOGO (WCP)	Not Necessary	75.00 F	*- F
4	1		*FRONT HEADLAMP RH (WCP)	Cracked	300.00 F	*300.00 F
5	1		*FRONT HEADLAMP LH (WCP)	Cut	300.00 F	*300.00 F
6	1		*FRONT BUMPER (WCP)	Cracked	360.00 F	*360.00 F
7	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Not Necessary	110.00 F	*- F
8	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Not Necessary	110.00 F	*- F
9	1		*FRONT AIRCON BLOWER (WCP)	Broken	940.00 F	*940.00 F
10	1		*FRONT COOLING COIL (WCP)	Broken	3,000.00 F	*3,000.00 F
11	1		*FRONT CORNER PANEL RH (WCP)	Dented	300.00 F	*300.00 F
12	1		*FRONT CORNER PANEL LH (WCP)	Not Necessary	300.00 F	*- F
<u>Supplementary #1</u>						
13	1		*DASHBOARD COVER (WCP)	Broken	240.00 F	*240.00 F
14	1		*FRONT BUMPER LOWER GRILLE FRONT BUMPER LOWER GRILLE(WCP)	Broken	505.00 F	*505.00 F
15	1		*CONDENSER (WCP)	Bent	420.00 F	*420.00 F
16	1		*BRAKE BOOSTER PUMP (WCP)	Dented	1,500.00 F	*1,500.00 F

F=Franchise part.

Sub Total (\$\$)	9,660.00	9,065.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	966.00	906.50
Total Parts (\$\$)	10,626.00	9,971.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT AIRCON GAS (NECESSARY)	60.00	60.00
2	1	FRONT NUMBER PLATE & HOLDER (NOT NECESSARY)	35.00	0.00
Sub Total (\$\$)			95.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	LABOUR FOR SPRAY PAINTING	New	1,000.00	600.00
Labour Items				
2	LABOUR FOR PANEL BEATING	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,000.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >