



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 3613X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	872.00	872.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	560.00	-
1	FRONT BUMPER REINFORCEMENT GARNISH LH (CONSISTENT)	NOT NECESSARY	56.00	-
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DAMAGED	24.00	24.00
1	FRONT BUMPER TOW COVER (CONSISTENT)	NOT NECESSARY	42.00	-
1	FRONT BUMPER LOWER LIP (CONSISTENT)	CUT	462.00	462.00
1	FRONT BUMPER LOWER LIP RUBBER (CONSISTENT)	NOT NECESSARY	126.00	-
1	FRONT BUMPER UNDER COVER GARNISH (CONSISTENT)	NOT NECESSARY	106.00	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT NECESSARY	210.00	-
1	FRONT BUMPER FOG LAMP LH (CONSISTENT)	NOT NECESSARY	362.00	-
1	FRONT BUMPER FOG LAMP OUTER GARNISH LH (CONSISTENT)	CUT	162.00	162.00
1	FRONT BUMPER FOG LAMP BRACKET LH (CONSISTENT)	NOT NECESSARY	98.00	-
1	FRONT SUPPORT PANEL TOP GARNISH RH (CONSISTENT)	NOT NECESSARY	112.00	-
1	FRONT SUPPORT PANEL SIDE GARNISH RH (CONSISTENT)	NOT NECESSARY	84.00	-
1	FRONT HEADLAMP LH(CONSISTENT)	CRACKED	1,999.00	1,859.00
1	FRONT HEADLAMP LOWER BRACKET LH (CONSISTENT)	NOT NECESSARY	56.00	-
1	FRONT HEADLAMP WIRE HARNESS (CONSISTENT)	NOT NECESSARY	711.30	-
1	FRONT FENDER RH (CONSISTENT)	NOT NECESSARY	389.00	-
1	FRONT FENDER OUTER GARNISH LH (CONSISTENT)	CUT	183.60	183.60
1	FRONT FENDER INNER SHIELD RH (CONSISTENT)	TORN	113.00	113.00
1	FRONT LOWER ARM LH (CONSISTENT)	NOT NECESSARY	654.50	-
1	FRONT SHOCK ABSORBER LH (CONSISTENT)	NOT NECESSARY	389.60	-
1	FRONT KNUCKLE ARM LH (CONSISTENT)	NOT NECESSARY	489.10	-
1	FRONT KNUCKLE ARM BEARING LH (CONSISTENT)	NOT NECESSARY	215.60	-
	LESS 20% DISCOUNT		-1,695.34	-735.12
			6,781.36	2,940.48



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	FRONT FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	FRONT FENDER OUTER GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	FRONT SPORT RIM RH (SN) (CONSISTENT)	NOT NECESSARY	650.00	-
1	FRONT TYRE RH (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
			1,080.00	80.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		1,500.00	300.00
	LABOUR FOR SPRAYPAINTING.		1,200.00	400.00
	WIRING CHECK.		80.00	30.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS .	NOT NECESSARY	300.00	-
	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			3,430.00	730.00
GRAND TOTAL			11,291.36	3,750.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/HSB23001069/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.