



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 5704L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP RH	SERVICEABLE	1,984.70	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	988.80	-
1	FRONT BUMPER	SERVICEABLE	891.10	-
1	FRONT BUMPER RETAINER RH	DISTORTED	47.60	47.60
1	FRONT FENDER RH	BENT	587.20	587.20
1	FRONT FENDER ART GARNISH RH	DENTED	168.90	168.90
1	FRONT FENDER COWLING RH	SERVICEABLE	114.20	-
1	FOGLAMP COVER RH	SERVICEABLE	78.20	-
1	FRT RH DOOR MIRROR	CRACKED	850.00	850.00
	LESS 20% DISCOUNT		-1,142.14	-330.74
			4,568.56	1,322.96
	<u>LABOUR</u>			
	TO REMOVE DAMAGED FRONT PARTS AND ATTACHMENTS. REPAIR / RESHAPE DENTED AREAS. STRAIGHTEN FRONT CHASSIS WHERE NECESSARY. TO REPLACE / REALIGN ALL PARTS INTO SAME POSITION. INCLUSIVE OF THE REPAIR OF FRONT BONNET. SPRAY PAINT.		800.00	500.00
			850.00	600.00
			1,650.00	1,100.00
	GRAND TOTAL		6,218.56	2,422.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/AGI23001070/Kwp3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.