

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001074/UQP3Q2**Date:** 28/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00193762201
<b>Claimant Vehicle No :</b>	SFP2P	<b>Insured Vehicle No :</b>	SLQ7977D
Date of Loss:	10/01/2023	Nature of Claim: TP	Claim No: SNM23D200278/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFP2P</b>		
Make & Model:	JEEP WRANGLER UNLIMITED SAHARA, 2.0 (A)	Engine No:	NLW150186
Reg. Date:	12/08/2020 (Man. Year: 2019)	Chassis No:	1C4HJXLN7LW150186
Colour:	Yellow	Odometer:	19202 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/70 R18	Rear Tyre Size:	255/70 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,552.50	1,790.95	2,761.55	60.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	730.00	780.00	51.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,062.50</b>	<b>2,520.95</b>	<b>3,541.55</b>	<b>58.42</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	6,062.50	2,000.00	4,062.50	67.01
<b>+ GST 8.00/8.00% (S\$)</b>	485.00	160.00	325.00	67.01
<b>Nett Amount (S\$)</b>	<b>6,547.50</b>	<b>2,160.00</b>	<b>4,387.50</b>	<b>67.01</b>

INSPECTION

Date of Assignment:	01/02/2023	
Date Inspected:	15/02/2023	Inspected At: Revo Performance Pte Ltd (HQ) BLK 1 KAKI BUKIT AVE 6 AUTOBAY #02-51 Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2023)
Parts:	M1-SUV	JEEP WRANGLER UNLIMITED SAHARA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFP2P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	903.00 F	*903.00 FL
2	1		*FRONT LICENSE PLATE HOLDER	Deformed	180.00 F	*180.00 FL
3	1		*FRONT BUMPER BEAM	Repair	738.00 F	*- FL
4	1		*FRONT BUMPER PANEL	Torn	234.00 F	*234.00 FL
5	1		*FRONT BUMPER INNER PROTECTOR	Torn	181.50 F	*181.50 FL
6	2		*FRONT BUMPER COVER ,CLOSE OUT	Not Necessary	270.00 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	420.00 F	*420.00 FL
8	6		*FRONT SENSOR ,PARK ASSIST	Not Necessary	1,539.00 F	*- FL
9	6		*RING ,DECOUPLER SENSOR	Necessary	27.00 F	*27.00 FL
10	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
			}			
11	1		*FRONT NUMBER PLATE SUPPORT		20.00 FS	*- FS
			}			
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,552.50	1,985.50
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	194.55
Total Parts (\$\$)					4,552.50	1,790.95
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	750.00	300.00
2	CHECK WIRING	New	60.00	0.00
3	TO REMOVE AND REPLACE BUMPER SENSOR	New	80.00	50.00
4	TO SPRAY PAINTING	New	620.00	380.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,510.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >