

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS4/CTI23001075/KWP3E2
Date: 18/04/2023**REFERENCE****Insured/Claimant:** Van-Go Pte Ltd **Policy No:** DMCVSNW00030172200
Date of Loss: 12/01/2023 **Nature of Claim:** OD **Claim No:** SNM23D200505/C01/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** GBL7324H
Make & Model: TOYOTA HIACE, 2.8 D (A) **Engine No:** 1GD8791353
Reg. Date: 02/03/2022 (Man. Year: 2021) **Chassis No:** GDH2011066392
Colour: Silver **Odometer:** 38258 km
Engine Capacity: 2754 cc
Market Value/New Car Price: S\$109,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 195 R15 **Rear Tyre Size:** 195 R15
Front Left Side: Grenlander 9 mm **Rear Left Side:** Grenlander 9 mm
Front Right Side: Grenlander 9 mm **Rear Right Side:** Grenlander 9 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,535.00	9,585.00	4,950.00	34.06
Miscellaneous Items	490.00	135.00	355.00	72.45
Labour	1,695.66	1,695.66	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,720.66	11,415.66	5,305.00	31.73
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	16,720.66	9,415.66	7,305.00	43.69
+ GST 8.00/8.00% (S\$)	1,337.65	753.25	584.40	43.69
Nett Amount (S\$)	18,058.31	10,168.91	7,889.40	43.69

INSPECTION**Date of Assignment:** 02/02/2023 **Present Location:** S & H Motor Pte Ltd (Sin Ming)
S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 02/02/2023 **Inspected At:** 160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 6.0 days**Adjuster:** KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,605.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Apr 2023)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL7324H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*parts		14,535.00 F	*9,585.00 F
F=Franchise part.						
Total Parts (S\$)					14,535.00	9,585.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	misc	490.00	135.00
Sub Total (S\$)			490.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	labour for part/mechanical	New	1,134.00	1,134.00
2	labour for paintworks	New	561.66	561.66
Gross Labour Cost (S\$)			1,695.66	1,695.66

Report was unsubmitted during this print-out.

< END OF ESTIMATES >