

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001077/UVP3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00088992201		
Claimant Vehicle No :	SMJ1928K	Insured Vehicle No :	SMT3472S		
Date of Loss:	28/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200741/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1928K	Engine No:	G4FGKU095052
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU866615
Reg. Date:	26/02/2019 (Man. Year: 2019)	Odometer:	103547 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,135.52	1,300.48	1,835.04	58.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,320.00	1,150.00	46.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,605.52	2,620.48	2,985.04	53.25
+ GST 8.00/8.00% (S\$)	448.44	209.64	238.80	53.25
Nett Amount (S\$)	6,053.96	2,830.12	3,223.84	53.25

INSPECTION

Date of Assignment:	01/02/2023		
Date Inspected:	27/02/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ1928K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE AVANTE LOGO	Not Necessary	38.20 FL	*- FL
2	1		*TAILGATE S LOGO	Not Necessary	38.20 FL	*- FL
3	1		*REAR BUMPER	Distorted	500.10 FL	*500.10 FL
4	2		*REAR BUMPER SIDE BRACKET -LH /RH	Not Necessary	58.80 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
6	1		*REAR BUMPER LOWER GARNISH	Distorted	353.50 FL	*353.50 FL
7	2		*REAR BUMPER LAMP -LH/RH	Serviceable	443.20 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	354.80 FL	*354.80 FL
9	1		*REAR END PANEL	Repair	454.60 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	59.80 FL	*- FL
11	1		*REAR KEYLESS SENSOR	Not Necessary	40.50 FL	*- FL
12	1		*REAR FENDER AIR VENT -LH	Not Necessary	45.90 FL	*- FL
13	1		*REAR BUMPER UNDERCOVER -LH	Torn	57.20 FL	*57.20 FL
14	10		*REAR BUMPER UNDERCOVER CLIPS	Necessary	30.00 FL	*30.00 FL
15	1		*REAR TAILLAMP -LH	Not Necessary	1,052.10 FL	*- FL
16	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
17	1		*REAR NUMBER PLATE WITH CASING	Bent	40.00 FS	*40.00 FS
					Sub Total (\$\$)	
					3,846.90	1,565.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	
					711.38	265.12
					Total Parts (\$\$)	
					3,135.52	1,300.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ON FLOOR PANEL & SIDE PANEL -LH ,CUT /WELD REAR PANEL ,REMOVE ,REPLAE ACCIDENT PARTS	New	1,200.00	550.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00	700.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE ,REPLACE REAR BUMPER SENSOR	New	120.00	50.00
5	TO TUFF-KOTE	New	100.00	0.00
Gross Labour Cost (\$\$)			2,470.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >