

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23001078/KNY3Q2**Date:** 03/04/2023**REFERENCE**

| | | | | |
|-------------------|-------------|------------------|--------------|-------------------------|
| Insured/Claimant: | ONG WEI KAR | Policy No: | DMPG22014211 | |
| Date of Loss: | 21/01/2023 | Nature of Claim: | OD | Claim No: CDMPG23000207 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SKG1092K | | |
| Make & Model: | MERCEDES-BENZ CLA200, 1.3 AMG LINE (A) | Engine No: | 28291480199422 |
| Reg. Date: | 29/04/2020 (Man. Year: 2019) | Chassis No: | WDD1183872N019395 |
| Colour: | Metallic Grey | Odometer: | 46446 km |
| Engine Capacity: | 1332 cc | | |
| Market Value/New Car Price: | S\$180,000.00 | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/45Z R18 | Rear Tyre Size: | 225/45Z R18 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 1,881.00 | 1,782.00 | 99.00 | 5.26 |
| Miscellaneous Items | 40.00 | 40.00 | 0.00 | 0.00 |
| Labour | 1,030.00 | 900.00 | 130.00 | 12.62 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 2,951.00 | 2,722.00 | 229.00 | 7.76 |
| - Excess (\$\$) | 0.00 | 500.00 | -500.00 | |
| (\$\$) | 2,951.00 | 2,222.00 | 729.00 | 24.70 |
| + GST 8.00/8.00% (\$\$) | 236.08 | 177.76 | 58.32 | 24.70 |
| Nett Amount (\$\$) | 3,187.08 | 2,399.76 | 787.32 | 24.70 |

INSPECTION

| | | | |
|-----------------------------|------------|-------------------|--|
| Date of Assignment: | 02/02/2023 | Present Location: | Cheng Hoe Motor Pte Ltd (Yishun) |
| Date Inspected: | 03/02/2023 | Inspected At: | Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761 |
| Estimated Period of Repair: | 4.0 days | | |

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 03 Apr 2023) |
| Parts: | 143 | MERCEDES-BENZ CLA200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKG1092K) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|---------------|--|-------------------|
| 1 | 1 | | *1 PC REAR WINDSCREEN GLASS | Broken | 540.00 F | *540.00 F |
| 2 | 1 | | *1 PC REAR BOOT | Bent | 1,080.00 F | *1,080.00 F |
| 3 | 1 | | *1 PC REAR BOOT LOGO | Not Necessary | 90.00 F | *- F |
| | | | | | | F=Franchise part. |
| | | | | | Sub Total (S\$) | 1,710.00 |
| | | | | | + Margin on L,N Items 10.00/10.00% (S\$) | 171.00 |
| | | | | | Total Parts (S\$) | 1,881.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|---|--------------|--------------|
| Miscellaneous Items | | | | |
| 1 | 1 | 1 PC REAR WINDSCREEN GUM (NECESSARY) | 40.00 | 40.00 |
| Sub Total (\$\$) | | | 40.00 | 40.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | 1) TO REMOVE AND REFIX REAR WINDSCREEN GLASS | New | 100.00 | 100.00 |
| 2 | 2) TO REMOVE AND REFIX REAR BOOT, TRANSFER LOCK ASSY, REFLECTORS, KNOCK AND REPAIR REAR LH FENDER AND RE-ALIGN TO SAME | New | 450.00 | 400.00 |
| 3 | 3) TO PUTTY AND RESPRAY ON REAR BOOT, REAR FENDERS | New | 480.00 | 400.00 |
| Gross Labour Cost (\$\$) | | | 1,030.00 | 900.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >