

Vehicle Damage Assessment Report for [SKG1092K]

Estimate Created: 26/03/2023 15:38 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 26/03/2023 15:44 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	CLA
Engine Type			
License Plate Number	SKG1092K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$2,722.00 WITH 4 WORKING
DAYS

Insurlogic 4 (26/03/2023 15:43)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear windscreen glass		1	540.00	10.00 %	594.00
Rear boot		1	1080.00	10.00 %	1,188.00
Parts Subtotal					1,782.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear windscreen sealant		1.0	40.00	0.00 %	40.00
Materials Subtotal					40.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove and refix rear windscreen glass.	RnR	100.00	0.00 %	100.00
Panel beating	RnR	400.00	0.00 %	400.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 500.00

Paint Labor Subtotal 400.00

Labor Subtotal 900.00

Summary

Repair Cost 2,722.00

Discount(0 %) (0.00)

2,722.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 2,722.00