

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23001082/UPA3Q2**Date:** 12/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0009933
Claimant Vehicle No : SJF6500J **Insured Vehicle No :** SML4595G
 Date of Loss: 09/01/2023 Nature of Claim: TP Claim No: MFL2023D0000302

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF6500J**
 Make & Model: MITSUBISHI COLT PLUS, 1.5 (A) Engine No: 4A910098683
 Reg. Date: 25/04/2008 (Man. Year: 2008) Chassis No: JMYLTZ23W8Z000470
 Colour: Blue Odometer: 100193 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,317.90	2,742.50	6,575.40	70.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,880.00	2,140.00	53.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,337.90	4,622.50	8,715.40	65.34
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	13,337.90	2,200.00	11,137.90	83.51
+ GST 8.00/8.00% (S\$)	1,067.03	176.00	891.03	83.51
Nett Amount (S\$)	14,404.93	2,376.00	12,028.93	83.51
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		2,822.75		
Global Sum Settlement (S\$)		2,820.00		

INSPECTION

Date of Assignment: 02/02/2023
 Date Inspected: 02/02/2023 Inspected At: Convergence Automotive Pte Ltd (HQ)
 39 Woodlands Close, MEGA@Woodlands #01-24
 Singapore 737856
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2023)
Parts:	144	MITSUBISHI COLT PLUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF6500J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	988.00 FL	*732.00 FL
2	2		*REAR BUMPER CORNER RETAINER L/R	Not Necessary	96.00 FL	*- FL
3	2		*REAR BUMPER INNER SHIELD L/R	Not Necessary	88.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	234.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Bent	58.00 FL	*58.00 FL
6	1		*REAR END PANEL	Dented	568.00 FL	*418.00 FL
7	1		*REAR END PANEL TOP GARNISH	Twisted	148.00 FL	*148.00 FL
8	1		*REAR END PANEL LOCK STRIKER	Not Necessary	28.00 FL	*- FL
9	1		*REAR EXHAUST GASKET	Not Necessary	25.00 FL	*- FL
10	3		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	150.00 FL	*- FL
11	1		*REAR EXHAUST BOX	Not Necessary	659.00 FL	*- FL
12	1		*TAILGATE	Dented	1,002.00 FL	*1,002.00 FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	108.00 FL	*- FL
14	1		*TAILGATE INNER HANDLE SWITCH	Not Necessary	58.00 FL	*- FL
15	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	276.00 FL	*276.00 FL
16	1		*TAILGATE LOCK	Dented / Jammed	370.00 FL	*205.00 FL
17	2		*TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	125.00 FL	*- FL
18	1		*TAILGATE OUTER GARNISH	Not Necessary	146.00 FL	*- FL
19	10		*TAILGATE OUTER GARNISH CLIP	Not Necessary	50.00 FL	*- FL
20	1		*TAILGATE OUTER LOCK HANDLE	Not Necessary	85.00 FL	*- FL
21	2		*TAILGATE REFLECTOR LAMP L/R	Not Necessary	458.00 FL	*- FL
22	2		*TAILGATE RUBBER STOPPER L/R	Not Necessary	48.00 FL	*- FL
23	1		*TAILGATE WEATHERSTRIPE	Not Necessary	236.00 FL	*- FL
24	2		*TAILGATE INNER WINDSCREEN GARNISH L/R	Not Necessary	124.00 FL	*- FL
25	1		*TAILGATE INNER WINDSCREEN TOP GARNISH	Not Necessary	96.00 FL	*- FL
26	1		*TAILGATE WINDSCREEN MOULDING	Necessary	175.00 FL	*86.00 FL
27	2		*TAILLAMP INNER PANEL L/R	Not Necessary	422.00 FL	*- FL
28	2		*TAILLAMP L/R	Not Necessary	758.00 FL	*- FL
29	1		*SPARE TYRE PANEL TOOLS TRAY	Not Necessary	418.00 FL	*- FL
30	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	332.00 FL	*- FL
31	1		*SPARE TYRE PANEL	Repair	1,002.00 FL	*- FL
32	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
33	1		*SET REVERSE SENSOR	Serviceable	300.00 FS	*- FS
34	1		*TAILGATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
35	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
36	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
37	1		*SPARE TYRE PANEL INSULATION MAT	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,251.00	3,035.00
- List Item Discount on L Items 10.00/10.00% (S\$)	933.10	292.50
Total Parts (S\$)	9,317.90	2,742.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING CHECK	New	120.00	20.00
2	REINSTALL REAR WINDSCREEN	New	200.00	120.00
3	REMOVE & REFIT REAR UPHOLSTERY	New	180.00	80.00
4	PANEL BEATING ON DAMAGED PORTION	New	1,700.00	800.00
5	SPRAY PAINTING ON DAMAGED PORTION	New	1,500.00	800.00
6	REMOVE & REFIT EXHAUST PIPE	New	120.00	0.00
7	ANTI RUST	New	200.00	60.00
Gross Labour Cost (S\$)			4,020.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >