

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23001086/CQY3M4**Date:** 22/03/2023**REFERENCE**

Insured/Claimant:	KOON PENG HWEE	Policy No:	SP2002871503
Date of Loss:	19/01/2023	Nature of Claim:	OD
		Claim No:	202332004953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW6356J	Engine No:	HR16954275C
Make & Model:	NISSAN SYLPHY, 1.6 CVT (A)	Chassis No:	MNTBBAB17Z0037574
Reg. Date:	30/11/2020 (Man. Year: 2020)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,689.50	1,509.20	1,180.30	43.89
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	1,400.00	900.00	500.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,124.50	2,444.20	1,680.30	40.74
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	4,124.50	1,844.20	2,280.30	55.29
+ GST 8.00/8.00% (\$\$)	329.96	147.54	182.42	55.29
Nett Amount (\$\$)	4,454.46	1,991.74	2,462.72	55.29

INSPECTION

Date of Assignment:	02/02/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	02/02/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun)
			Blk 1019 #01-374/382, Yishun Industrial Park A
			Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: SIMON HO LEONG CHUAN**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW6356J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER (WCP)	Distorted	350.00 F	*350.00 F
2	1		*1 PC FRT BUMPER REINFORCEMENT (WCP)	Repair	280.00 F	*- F
3	1		*1 PC FRT BUMPER SPONGE (WCP)	Cracked	100.00 F	*80.00 F
4	1		*6 PCS FRT BUMPER CLIPS @2/PC (WCP)	Necessary	12.00 F	*12.00 F
5	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE (WCP)	Not Necessary	115.00 F	*- F
6	1		*1 PC FRT TOW COVER (WCP)	Not Necessary	25.00 F	*- F
7	1		*1 PC FRT GRILLE (WCP)	Cracked	320.00 F	*320.00 F
8	1		*1 PC FRT GRILLE LOGO (WCP)	Not Necessary	50.00 F	*- F
9	1		*4 PCS FRT GRILLE CLIPS @2/PC (WCP)	Not Necessary	8.00 F	*- F
10	1		*1 PC FRT SUPPORT TOP GARNISH (WCP)	Cut	130.00 F	*130.00 F
11	1		*1 PC BONNET (WCP)	Buckled	480.00 F	*480.00 F
12	1		*1 PC LH HEADLAMP (WCP)	Not Necessary	520.00 F	*- F
13	1		*1 PC LH FOG LAMP GARNISH (WCP)	Not Necessary	55.00 F	*- F
F=Franchise part.						
Sub Total (S\$)					2,445.00	1,372.00
+ Margin on L,N Items 10.00/10.00% (S\$)					244.50	137.20
Total Parts (S\$)					2,689.50	1,509.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NUMBER PLATE (CRACKED)	35.00	35.00
Sub Total (\$\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY, FOG LAMPS, GRILLE, BONNET & ATTACHMENT, HEADLAMPS, TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME	New	600.00	400.00
2	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00	0.00
3	PUTTY & RESPRAY ON FRT SUPPORT PANEL, FRT BUMPER, FRT BONNET	New	700.00	500.00
Gross Labour Cost (\$\$)			1,400.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >