

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001088/UQP3Q2**Date:** 09/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00147682100	
Claimant Vehicle No :	FBR856D	Insured Vehicle No :	XE3257X	
Date of Loss:	14/09/2022	Nature of Claim:	TP	Claim No: SNM22D206630/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR856D		Engine No:	G3P3E0001140
Make & Model:	YAMAHA JUPITER T150, 150cc		Chassis No:	MH3UG131000001117
Reg. Date:	14/02/2020 (Man. Year: 2019)		Odometer:	77791 km
Colour:	Grey			
Engine Capacity:	150 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90-80-17	Rear Tyre Size:	120/70Z R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,262.80	3,414.80	3,848.00	52.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	350.00	530.00	60.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,142.80	3,764.80	4,378.00	53.77
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	8,142.80	3,000.00	5,142.80	63.16

INSPECTION

Date of Assignment:	02/02/2023		
Date Inspected:	02/02/2023	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Feb 2023)	
Parts:	N/A	YAMAHA JUPITER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR856D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Repair	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Repair	185.00 FL	*- FL
3	1		*HANDLE -BAR	Bent	168.00 FL	*168.00 FL
4	1		*HANDLE -BAR END	Scratched	60.00 FL	*40.00 FL
5	1		*SET HAND GRIP	Cut	68.00 FL	*68.00 FL
6	1		*SET SIDE MIRROR	Cut	128.00 FL	*80.00 FL
7	1		*BRAKE LEVER	Cut	78.00 FL	*78.00 FL
8	1		*CLUTCH LEVER	Cut	78.00 FL	*78.00 FL
9	1		*FRONT SIGNAL (O/S)	Cracked	160.00 FL	*90.00 FL
10	1		*PILOT LIGHT	Cracked	380.00 FL	*180.00 FL
11	1		*HORN INNER PANEL	Cracked	150.00 FL	*110.00 FL
12	1		*SET FAIRING ASSY	Cracked	680.00 FL	*520.00 FL
13	1		*FRONT SIDE COVER (MATT)	Cracked	125.00 FL	*82.00 FL
14	1		*FRONT SIDE LOWER COVER (MATT)	Cracked	165.00 FL	*115.00 FL
15	1		*FRONT FOOTREST BRACKET	Bent	186.00 FL	*160.00 FL
16	1		*FRONT FOOTREST	N/S Cut	148.00 FL	*50.00 FL
17	1		*GEAR PEDAL	Bent	88.00 FL	*88.00 FL
18	2		*REAR FOOTREST	Not Necessary	150.00 FL	*- FL
19	2		*REAR FOOTREST BRACKET	Not Necessary	360.00 FL	*- FL
20	1		*EXHAUST ASSY	Repair	685.00 FL	*- FL
21	1		*EXHAUST PROTECTOR -REAR	Cut	90.00 FL	*90.00 FL
22	1		*EXHAUST PROTECTOR -FRONT	Cut	75.00 FL	*75.00 FL
23	1		*EXHAUST PIPE END COVER	Repeated	65.00 FL	*- FL
24	1		*ENGINE COVER	Cut	550.00 FL	*380.00 FL
25	1		*BASKET	Cracked	125.00 FL	*60.00 FL
26	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
27	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
28	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
29	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
30	1		*E.R.P IU	Cut	180.00 FS	*165.00 FS
31	1		*ENGINE OIL	Necessary	30.00 FS	*10.00 FS
32	1		*ENGINE GASKET	Necessary	85.00 FS	*85.00 FS
33	1		*REAR BOX	Cut	580.00 FS	*300.00 FS
34	1		*REAR BOX BRACKET	Bent	180.00 FS	*120.00 FS
35	1		*CLUTCH COVER	Cut	750.00 FL	*390.00 FL
36	1		*ENGINE OIL FILTER COVER	Cut	145.00 FL	*70.00 FL
37	1		*CLUTCH COVER GASKET	Cut	105.00 FS	*60.00 FS
38	1		*ENGINE OIL FILTER	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,911.00	3,712.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	648.20	297.20
Total Parts (\$\$)	7,262.80	3,414.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	420.00	350.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
Gross Labour Cost (S\$)			880.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >