

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001093/UQP3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00106562200

Claimant Vehicle No : SMU8526H **Insured Vehicle No :** SDD717Y

Date of Loss: 20/01/2023 Nature of Claim: TP Claim No: SNM23D200587/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU8526H**

Make & Model: HONDA FIT, 1.3 (A) Engine No: L13B1501361

Reg. Date: 31/08/2020 (Man. Year: 2020) Chassis No: GR11000780

Colour: Grey Odometer: 26378 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Firenza 7 mm Rear Left Side: Firenza 7 mm

Front Right Side: Firenza 7 mm Rear Right Side: Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,232.00	1,800.80	431.20	19.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,680.00	1,170.00	41.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,082.00	3,480.80	1,601.20	31.51
+ GST 8.00/8.00% (\$\$)	406.56	278.46	128.10	31.51
Nett Amount (\$\$)	5,488.56	3,759.26	1,729.30	31.51

INSPECTION

Date of Assignment: 02/02/2023

Date Inspected: 03/02/2023 Inspected At: ETHOZ Protect Pte Ltd (Tampines)
22 Tampines St 92
Singapore 528876

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU8526H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented / Bent	1,125.00 FL	*1,050.50 FL
2	1		*FRONT DOOR STICKER SET RH	Necessary	135.00 FL	*110.00 FL
3	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	187.50 FL	*- FL
4	1		*REAR DOOR RH	Dented /Bent	1,020.00 FL	*980.50 FL
5	1		*REAR DOOR STICKER SET RH	Necessary	135.00 FL	*110.00 FL
6	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	187.50 FL	*- FL
7	1		*ROCKER PANEL RH (NPA)	Repair	0.00 FL	*- FL
8	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
9	1		*3REAR BUMPER (NPA)	Not Necessary	0.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	2,790.00 2,251.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	558.00 450.20
					Total Parts (S\$)	2,232.00 1,800.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	580.00
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	900.00
3	TO REMOVE AND TRANSFER BOTH RH DOOR COMPONENTS	New	300.00	120.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	20.00
5	RUST PROOFING	New	100.00	60.00
Gross Labour Cost (S\$)			2,850.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >