



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 2615K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED	585.50	585.50
1	REAR BUMPER LOWER	MISSING	315.20	315.20
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	285.85	-
1	REAR BUMPER LOWER BRACKET LH	SERVICEABLE	18.50	-
1	REAR BUMPER LOWER BRACKET RH	DISTORTED	18.50	18.50
1	REAR BUMPER CENTRE BRACKET	SERVICEABLE	18.50	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	28.50	28.50
5	REAR BUMPER CLIPS @\$4.85	NECESSARY	24.25	24.25
	LESS 10% DISCOUNT		-129.48	-97.19
			1,165.32	874.76
	<b><u>LABOUR</u></b>			
	TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		250.00	200.00
	TO SPRAY PAINT (PEARL WHITE).		300.00	240.00
			550.00	440.00
	<b>GRAND TOTAL</b>		<b>1,715.32</b>	<b>1,314.76</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,314.76</b>

Report Ref No. CS/AGI23001095/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.