

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001097/UWP3Q2**Date:** 23/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00002542302		
<b>Claimant Vehicle No :</b>	SLM9763L	<b>Insured Vehicle No :</b>	GBK9281P		
Date of Loss:	30/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200831/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLM9763L</b>	Engine No:	G4FGGH655501
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MH5705712
Reg. Date:	19/04/2017 (Man. Year: 2017)	Odometer:	46144 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,233.25	4,109.95	2,123.30	34.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,690.00	570.00	25.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,493.25</b>	<b>5,799.95</b>	<b>2,693.30</b>	<b>31.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
<b>(S\$)</b>	8,493.25	4,600.00	3,893.25	45.84
<b>+ GST 8.00/8.00% (S\$)</b>	679.46	368.00	311.46	45.84
<b>Nett Amount (S\$)</b>	<b>9,172.71</b>	<b>4,968.00</b>	<b>4,204.71</b>	<b>45.84</b>

**INSPECTION**

Date of Assignment:	09/02/2023		
Date Inspected:	20/02/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
<b>Parts:</b> 143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLM9763L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	681.00 FL	*681.00 FL
2	1		*REAR BUMPER LOWER ,BLACK	Distorted	313.00 FL	*313.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
4	2		*REAR BUMPER SIDE HOLDER -LH/RH	Bent	52.00 FL	*52.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	287.00 FL	*287.00 FL
6	2		*REAR BUMPER REINFORCEMENT BRACKET - LH/RH	Bent	216.00 FL	*216.00 FL
7	3		*REAR BUMPER INNER TOP BRACKET ,SMALL	Twisted	19.50 FL	*19.50 FL
8	2		*REAR BUMPER INNER LOWER BRACKET ,SMALL	Twisted	13.00 FL	*13.00 FL
9	1		*REAR BOOT	Dented	1,366.00 FL	*1,366.00 FL
10	1		*REAR BOOT RUBBER	Twisted	90.00 FL	*90.00 FL
11	1		*REAR BOOT TOP LOCK	Bent	101.00 FL	*101.00 FL
12	1		*REAR BOOT BOTTOM LOCK	Not Necessary	40.00 FL	*- FL
13	1		*REAR BOOT CERATO WORDINGS	Necessary	28.00 FL	*28.00 FL
14	1		*REAR BOOT K3 WORDINGS	Necessary	35.00 FL	*35.00 FL
15	1		*REAR BOOT REFLECTORS -LH/RH	N/S Cracked /O/SNot Necessary	1,422.00 FL	*711.00 FL
16	2		*TAIL LAMP -LH/RH	Not Necessary	1,578.00 FL	*- FL
17	1		*TAIL LAMP CLIP-LH/RH	Not Necessary	8.00 FL	*- FL
18	1		*REAR PANEL	Dented	292.00 FL	*292.00 FL
19	1		*REAR PANEL TOP GARNISH	Twisted	52.00 FL	*52.00 FL
20	1		*SET REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS
21	1		*REAR NUMBER PLATE WITH CASING	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,897.50</b>	<b>4,540.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	664.25	430.55
<b>Total Parts (\$\$)</b>	<b>6,233.25</b>	<b>4,109.95</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS ,REAR PANEL,REMOVE ,REPLACE ACCIDENT PARTS	New	900.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00	900.00
3	TO REMOVE,REFIX REAR GARNISH AND RELATED PARTS	New	100.00	60.00
4	TO TUFF -KOTE	New	60.00	60.00
5	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
6	TO RESET CHECKLIGHT	New	100.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,260.00</b>	<b>1,690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >