

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23001098/ANY3Q2**Date:** 31/05/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SLK7492S**Insured Vehicle No :** XD1506X

Date of Loss: 18/01/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLK7492S**

Make & Model: PEUGEOT 5008, 1.6 D BLUEHDI EAT6 S/R (A) Engine No: 10JBHX3012666

Reg. Date: 25/01/2017 (Man. Year: 2016) Chassis No: VF30EBHZTGS198172

Colour: Black Odometer: 145969 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	988.83	854.01	134.82	13.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	230.00	220.00	48.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,438.83	1,084.01	354.82	24.66
Approved Total (Overridden) (S\$)		850.00		
(S\$)	1,438.83	850.00	588.83	40.92
+ GST 8.00/8.00% (S\$)	115.11	68.00	47.11	40.93
Nett Amount (S\$)	1,553.94	918.00	635.94	40.92

INSPECTION

Date of Assignment: 02/02/2023

Date Inspected: 10/02/2023 Inspected At:

Mirage Motorwerkz Pte Ltd (HQ)
10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST
CENTRE
Singapore 417868

Estimated Period of Repair: 1.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	M1-SUV	PEUGEOT 5008 1.6 D BLUEHDI EAT6 S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK7492S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR ASSY	Distorted	948.90 FL	*948.90 FL
2	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	149.80 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,098.70	948.90
- List Item Discount on L Items 10.00/10.00% (S\$)					109.87	94.89
Total Parts (S\$)					988.83	854.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	200.00	100.00
2	SPRAY PAINTING	New	200.00	100.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			450.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >