

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001099/UQP3E2**Date:** 18/05/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00238682104

**Claimant Vehicle
No :** JSL3865**Insured Vehicle
No :** SLU7910A

Date of Loss: 05/10/2022

Nature of Claim: TP

Claim
No: SNM22D207169/C02/TOHHSDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **JSL3865**

Make & Model: YAMAHA Y15ZR, 150cc

Engine No: G3D3E117539

Reg. Date: 21/11/2017 (Man. Year: 2017)

Chassis No: PMYUG0510H0117619

Colour: Blue

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	80-90-17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,455.10	6,125.90	3,329.20	35.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	350.00	560.00	61.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,365.10	6,475.90	3,889.20	37.52
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	10,365.10	3,000.00	7,365.10	71.06

INSPECTION

Date of Assignment: 05/02/2023

Date Inspected: 02/02/2023 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2023)	
Parts:	N/A	YAMAHA Y15ZR 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JSL3865)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Twisted	640.00 FL	*480.00 FL
2	1		*FORK UNDER BRACKET	Bent	185.00 FL	*155.00 FL
3	1		*FRONT FENDER BRACKET	Bent	125.00 FL	*125.00 FL
4	1		*FRONT WHEEL RIM	Cracked	380.00 FL	*305.00 FL
5	1		*FRONT RIM SHAFT	Bent	65.00 FL	*38.00 FL
6	1		*FRONT RIM BEARING	Necessary	90.00 FL	*50.00 FL
7	1		*FRONT BRAKE DISC	Warped	185.00 FL	*125.00 FL
8	1		*BRAKE MASTER PUMP BRACKET	Serviceable	95.00 FL	*- FL
9	1		*CALIPER	Serviceable	520.00 FL	*- FL
10	1		*HANDLE BAR	Bent	165.00 FL	*165.00 FL
11	1		*SET HANDLE-BAR END	Cut	105.00 FL	*30.00 FL
12	1		*SET HAND GRIP	Torn	85.00 FL	*50.00 FL
13	1		*HEADLAMP ASSY	Cracked	580.00 FL	*320.00 FL
14	1		*HEADLAMP COVER	Cracked	135.00 FL	*135.00 FL
15	1		*HEADLAMP INNER COVER	Cracked	145.00 FL	*115.00 FL
16	1		*HORN	Dented	95.00 FL	*60.00 FL
17	1		*METER ASSY	Cracked	580.00 FL	*420.00 FL
18	1		*MIRROR	Broken	150.00 FL	*80.00 FL
19	1		*BRAKE LEVER	Cracked	85.00 FL	*85.00 FL
20	1		*SET FRONT SIGNAL	Cracked	140.00 FL	*80.00 FL
21	1		*PILOT LIGHTS	Cracked	228.00 FL	*145.00 FL
22	1		*BASKET	Distorted	125.00 FL	*60.00 FL
23	1		*FRONT COVER INNER BRACKET	Bent	280.00 FL	*110.00 FL
24	2		*FRONT SIDE COVER - MATT	Broken	145.00 FL	*145.00 FL
25	2		*FRONT SIDE LOWER COVER - MATT BLACK	Broken	180.00 FL	*180.00 FL
26	1		*FRONT HORN INNER COVER CENTRE MATT BLACK	Broken	85.00 FL	*85.00 FL
27	1		*FRONT HORN INNER COVER	Cracked	135.00 FL	*135.00 FL
28	1		*SEAT	Torn	280.00 FL	*160.00 FL
29	1		*PILLIONS FOOTREST BRACKET	Bent	180.00 FL	*115.00 FL
30	1		*SET PILLION FOOTREST	Cut	98.00 FL	*60.00 FL
31	1		*RECTIFIER	Cracked	385.00 FL	*385.00 FL
32	1		*RADIATOR	Bent / Punctured	580.00 FL	*420.00 FL
33	1		*EXHAUST ASSY	Dented	685.00 FL	*465.00 FL
34	1		*EXHAUST COVER	Scratched	115.00 FL	*60.00 FL
35	1		*EXHAUST END CAP	Scratched	75.00 FL	*38.00 FL
36	1		*SET RIDER FOOTREST	Cut	88.00 FL	*60.00 FL
37	1		*SET RIDER FOOTREST BRACKET	Not Necessary	170.00 FL	*- FL
38	1		*BRAKE PEDAL	Bent	125.00 FL	*90.00 FL
39	1		*SET REAR SIGNALS	O/S Broken	140.00 FL	*85.00 FL
40	1		*SET FAIRING ASSY	Broken	580.00 FL	*485.00 FL
41	1		*SET NUMBER PLATE	Bent / Necessary	38.00 FS	*20.00 FS
42	2		*FORK OILS	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
44	1		*SET STEERING CONE	Necessary	95.00 FS	*60.00 FS
45	1		*FRONT TYRE (50%)	Punctured / Cut	150.00 FS	*75.00 FS
46	1		*REAR BOX	Cut	480.00 FS	*300.00 FS
47	1		*REAR BOX BRACKET	Twisted	180.00 FS	*120.00 FS
48	1		*SET STICKER	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,378.00	6,736.00
- List Item Discount on L Items 10.00/10.00% (S\$)	922.90	610.10
Total Parts (S\$)	9,455.10	6,125.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO REPAIR BODY FRAME	New	350.00	0.00
3	TO PROVIDE LABOUR	New	480.00	350.00
Gross Labour Cost (\$)			910.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >