



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7311M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE-BAR	BENT	395.00	290.00
1	SET HANDLE BAR PROTECTOR	CUT	480.00	200.00
1	SIDE MIRRORS (O/S)	CUT	320.00	145.00
1	FRONT SIGNAL (O/S)	CUT	360.00	150.00
1	WINDSCREEN	CRACKED	220.00	220.00
1	SET SPORT LIGHT	DAMAGED	680.00	400.00
1	FRONT SIDE COVER	CUT	286.00	182.00
1	FRONT INNER COVER	CRACKED	428.00	290.00
1	FRONT FOOTRESTS	CUT	120.00	80.00
1	FRONT FOOTREST BRACKET	BENT	320.00	155.00
1	BRAKE PEDAL	BENT	220.00	160.00
1	EXHAUST ASSY	BENT	1,200.00	900.00
1	EXHAUST PROTECTOR	BENT	220.00	120.00
1	REAR FOOTREST	NOT NECESSARY	125.00	-
1	REAR FOOTREST BRACKET	CRACKED	280.00	160.00
1	REAR SIDE COVER	CUT	420.00	420.00
1	ENGINE COVER	TO REPAIR SEE LABOUR	680.00	-
1	REAR RIM	BENT	720.00	720.00
1	REAR RIM SHAFT	BENT	180.00	45.00
1	REAR RIM BEARING	DAMAGED	105.00	60.00
1	REAR BRAKE DISC	NOT NECESSARY	325.00	-
1	REAR SWING ARM	BENT	980.00	980.00
	LESS 10% DISCOUNT		-906.40	-567.70
			8,157.60	5,109.30
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	FRONT NECESSARY	38.00	10.00
1	CRASH BAR - 1 SET UPPER & LOWER (SN)	BENT	1,150.00	680.00
1	REAR TYRE (SN)	SERVICEABLE	385.00	-
1	SET REAR SIDE BOX BRACKET (SN)	CUT/BENT	850.00	400.00

Report Ref No. CS/AGI23001106/Uqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX (SN)	DENTED	580.00	450.00
1	REAR BOX BRACKET (SN)	BENT	280.00	120.00
			3,283.00	1,660.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE (LOD) S\$60.00 (NPA).	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	500.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF ENGINE COVER.		600.00	400.00
			1,180.00	400.00
GRAND TOTAL			12,620.60	7,169.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CS/AGI23001106/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.