

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|-----------------|------|--------------------|--|
| | EQ INSURANCE C | OMPANY LTD | R | lef: | CS3/EQI23001107/y3 | |
| | 5 MAXWELL ROAL #17-00 TOWER BL MND COMPLEXSI | OCK | D | ate: | 02/02/2023 | |
| | | | С | ode: | EQI | |
| 1. | 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SNA 2286H | Veh. Inspected | | SND 7071L | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | DM23HO00233 | Excess (\$) | | 0.00 | |
| | Assign From | NEO JIE SI | Assign Date | | 02/02/2023 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | Colour | | | | |
| | Odometer - | | Steering | | | |
| | Brakes | Modification | | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 17/01/2023 | Inspection Date | | 28/02/2023 | |
| | Survey held at MASTER CAR SPRAY SERVICE | | | | | |
| | | 40 TOH GUAN ROAD EAST #01-67 ENTERPRISE HUB SINGAPORE 608582 | | | | |
| 5a. | | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | |