

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23001113/APA3Q2**Date:** 20/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MCV0002869
Claimant Vehicle No : SLB2671Y **Insured Vehicle No :** GBC417S
 Date of Loss: 31/01/2023 Nature of Claim: TP Claim No: MCV2023D0001352

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB2671Y**
 Make & Model: VOLKSWAGEN GOLF, 1.2 TSI (A) Engine No: CYV088906
 Reg. Date: 31/03/2016 (Man. Year: 2015) Chassis No: WVWZZZAUZGW204882
 Colour: White Odometer: 100088 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,761.66	8,453.61	6,308.05	42.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,520.00	1,740.00	53.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,021.66	9,973.61	8,048.05	44.66
Approved Total (Overridden) (S\$)		7,900.00		
Nett Amount (S\$)	18,021.66	7,900.00	10,121.66	56.16
+ Car Rental (7.0 x S\$100.00/day + 8.00% GST) (S\$)		756.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		8,682.75		
Global Sum Settlement (S\$)		8,600.00		

INSPECTION

Date of Assignment: 02/02/2023
 Date Inspected: 02/02/2023 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	144	VOLKSWAGEN GOLF 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB2671Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,368.23 FL	*1,098.00 FL
2	1		*FRONT BUMPER GRILLE	Cut	476.35 FL	*476.35 FL
3	1		*FRONT BUMPER GRILLE LOGO	Necessary	155.20 FL	*155.20 FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	395.33 FL	*- FL
5	2		*FRONT BUMPER CORNER BRACKET	Not Necessary	370.60 FL	*- FL
6	2		*FRONT BUMPER FOGLAMP GARNISH	Not Necessary	340.60 FL	*- FL
7	1		*FRONT BUMPER BOTTOM GARNISH	Not Necessary	417.05 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	840.43 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	231.75 FL	*231.75 FL
10	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	188.72 FL	*- FL
11	1		*FRONT FENDER LH	Buckled	694.33 FL	*694.33 FL
12	2		*FRONT FENDER INNER COWLING	Not Necessary	381.96 FL	*- FL
13	1		*FRONT WINDSCREEN SIDE MOULDING	Not Necessary	178.20 FL	*- FL
14	2		*HEADLAMP	Cracked	3,137.50 FL	*3,137.50 FL
15	2		*HEADLAMP LOWER BRACKET	Not Necessary	361.76 FL	*- FL
16	1		*BONNET	Dented	1,849.98 FL	*1,380.00 FL
17	2		*BONNET HINGE	Bent	366.80 FL	*366.80 FL
18	2		*BONNET SIDE RUBBER	Not Necessary	175.00 FL	*- FL
19	1		*BONNET INSULATOR	Not Necessary	490.88 FL	*- FL
20	1		*BONNET BOTTOM LOCK	Damaged	302.88 FL	*302.88 FL
21	2		*HORN	Not Necessary	280.26 FL	*- FL
22	1		*FRONT BRACE PANEL	Bent	135.55 FL	*135.55 FL
23	1		*FRONT SUPPORT PANEL	Cracked	1,311.63 FL	*1,048.00 FL
24	1		*FRONT SUPPORT PANEL CENTER BEAM	Bent	199.87 FL	*199.87 FL
25	1		*AIR CON CONDENSER	Not Necessary	980.15 FL	*- FL
26	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	137.50 FL	*- FL
27	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*60.00 FS
28	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*SET FRONT BUMPER BOTTOM GARNISH CLIP	Not Necessary	30.00 FS	*- FS
30	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
31	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*HEADLAMP TOP GARNISH (SPECAIL TYPE)	Not Necessary	80.00 FS	*- FS
33	1		*SET FRONT GRILLE CLIP (UPPER)	Necessary	30.00 FS	*20.00 FS
34	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
35	1		*SET AIR CON CONDENSER SIDE GARNISH CLIP	Not Necessary	30.00 FS	*- FS
36	1		*COOLANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,338.51	9,376.23
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,576.85	922.62
Total Parts (\$\$)	14,761.66	8,453.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACED PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			3,260.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >