

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23001133/RVY3E2**Date:** 16/02/2023**REFERENCE**

Insured/Claimant:	LOO CHERN LIANG	Policy No:	DMPG22010587	
Date of Loss:	31/01/2023	Nature of Claim:	OD	Claim No: CDMPG23000246

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV9910E	Engine No:	1NZY036071
Make & Model:	TOYOTA VIOS E, 1.5 (A)	Chassis No:	MR053HY9305149960
Reg. Date:	26/02/2010 (Man. Year: 2009)	Odometer:	395179 km
Colour:	Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,247.00	5,810.80	2,436.20	29.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	2,090.00	360.00	14.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,697.00	7,900.80	2,796.20	26.14
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	10,697.00	7,400.80	3,296.20	30.81
+ GST 8.00/8.00% (S\$)	855.76	592.06	263.70	30.81
Nett Amount (S\$)	11,552.76	7,992.86	3,559.90	30.81

INSPECTION

Date of Assignment:	02/02/2023	
Date Inspected:	03/02/2023	Inspected At: Mova Automotive Pte Ltd 15 Fan Yong Road Singapore 629792
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Insured had withdrawn OD claim

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,411.20 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2023)
Parts:	143	TOYOTA VIOS E 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV9910E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	420.00 F	*420.00 F
2	1		*FRONT BONNET HINGE LH (WCP)	Bent	62.00 F	*62.00 F
3	1		*FRONT BONNET HINGE RH (WCP)	Bent	62.00 F	*62.00 F
4	1		*FRONT BONNET LOCK (WCP)	Jammed	95.00 F	*95.00 F
5	1		*FRONT GRILLE (WCP)	Cracked	185.00 F	*185.00 F
6	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	72.00 F	*72.00 F
7	1		*FRONT GRILLE MOULDING (WCP)	Cracked	110.00 F	*110.00 F
8	1		*FRONT GRILLE INNER RETAINER GUIDE (WCP)	* Check	160.00 F	*- F
9	1		*FRONT BUMPER (WCP)	Cracked	280.00 F	*280.00 F
10	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	275.00 F	*275.00 F
11	1		*FRONT BUMPER TOWING COVER (WCP)	Missing	32.00 F	*32.00 F
12	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	110.00 F	*110.00 F
13	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Necessary	75.00 F	*75.00 F
14	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Necessary	75.00 F	*75.00 F
15	1		*FRONT BUMPER CLIPS (WCP)	Necessary	40.00 FS	*30.00 FS
16	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*35.00 FS
17	1		*FRONT NUMBER PLATE HOLDER }		20.00 FS	*- FS
18	1		*FRONT HORN (WCP)	Not Working	145.00 F	*145.00 F
19	1		*FRONT SUPPORT PANEL (WCP)	Bent	420.00 F	*420.00 F
20	1		*FRONT HEADLAMP LH (WCP)	Cracked	260.00 F	*260.00 F
21	1		*FRONT HEADLAMP RH (WCP)	Cracked	260.00 F	*260.00 F
22	1		*FRONT HEADLAMP UPPER PANEL LH (WCP)	Bent	120.00 F	*120.00 F
23	1		*FRONT HEADLAMP UPPER PANEL RH (WCP)	Bent	120.00 F	*120.00 F
24	1		*FRONT A/COND CONDENSOR (WCP)	Bent	650.00 F	*650.00 F
25	1		*FRONT A/COND LIQUID PIPE (WCP)	* Check	320.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT A/COND PRESSURE PIPE (WCP)	* Check	340.00 F	*- F
27	1		*FRONT RADIATOR (WCP)	Bent	750.00 F	*750.00 F
28	1		*FRONT RADIATOR COOLANT (WCP)	Necessary	50.00 FS	*50.00 FS
29	1		*FRONT RADIATOR FAN GUARD (WCP)	* Check	220.00 F	*- F
30	1		*FRONT RADIATOR FAN ASSY (WCP)	* Check	180.00 F	*- F
31	1		*FRONT RADIATOR TOP HOSE (WCP)	* Check	42.00 F	*- F
32	1		*FRONT RADIATOR TOP HOSE CONNECTOR (WCP)	* Check	68.00 F	*- F
33	1		*FRONT INLET MANIFOLD (WCP)	* Check	380.00 F	*- F
34	1		*FRONT WIPER TANK (WCP)	Deformed	78.00 F	*78.00 F
35	1		*FRONT AIR CLEANER ASSY (WCP)	* Check	390.00 F	*- F
36	1		*FRONT AIR CLEANER DUCT (WCP)	* Check	92.00 F	*- F
37	1		*FRONT FENDER RH (WCP)	Bent	240.00 F	*240.00 F
38	1		*FRONT WIPER AIR GRILLE (WCP)	Cut	220.00 F	*220.00 F
39	1		*FRONT WIPER AIR GRILLE SIDE COVER RH (WCP)	Cut	62.00 F	*62.00 F
40	1		*FRONT FENDER LH - REPAIR (NPA)	Repair	-	*- F
41	1		*FRONT WHEEL HOUSE CHASSIS LH/RH - REPAIR (NPA)	Repair	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,510.00	5,293.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	737.00	517.80
Total Parts (\$\$)	8,247.00	5,810.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACE & REFIT FRONT RADIATOR, RADIATOR FAN ASSY, AIR COND CONDENSOR, AIR COND PIPE & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL & ETC.	New	120.00	100.00
2	TO REMOVE, REPLACE INLET MANIFOLD, AIR CLEANER ASSY, BATTERY & ETC. BACK TO ORIGINAL OPERATIONS	New	100.00	60.00
3	TO REMOVE, RPELACE, REPAIR, READJUST & CHISEL FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH, FRONT WHEEL HOUSE CHASSIS LH&RH & ETC. BACK TO ORIGINAL CONDITIONS	New	850.00	800.00
4	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH & CHASSIS MEMBER LH&RH	New	1,200.00	1,000.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	30.00
6	TO REFILL AIR COND GAS & VACUUM	New	100.00	100.00
Gross Labour Cost (\$\$)			2,450.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >