

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23001134/UPA3Q2**Date:** 06/06/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No: SP2001143287

Claimant Vehicle No : SDE8885L**Insured Vehicle No :** SJJ1000Y

Date of Loss: 23/01/2023

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDE8885L**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B25521001

Reg. Date: 04/10/2021 (Man. Year: 2021)

Chassis No: MRHFC5650LT000708

Colour: Blue

Odometer: 13038 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	697.66	185.62	512.04	73.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,840.00	1,040.00	36.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,577.66	2,025.62	1,552.04	43.38
+ GST 8.00/8.00% (S\$)	286.21	162.05	124.16	43.38
Nett Amount (S\$)	3,863.87	2,187.67	1,676.20	43.38
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,369.67		

INSPECTION

Date of Assignment: 31/01/2023

Date Inspected: 14/03/2023

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4

Singapore 408610

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDE8885L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ,FR .BUMPER	Repair	434.92 FS	*- FS
2	1		*SPACERL,FR.BUMPER SIDE	Not Necessary	7.80 FS	*- FS
3	17		*CLIP BUMPER	Not Necessary	29.32 FS	*- FS
4	1		*LIGHT ASSYL.SIDE TURN	Scratched	50.62 FS	*50.62 FS
5	1		*NUMBER PLATE -OPC	Necessary	45.00 FS	*45.00 FS
6	1		*SEAL NUMBER PLATE	Necessary	80.00 FS	*80.00 FS
7	1		*SUNDRIES	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	697.66	185.62
-------------------	--------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	150.00
2	STRAIGHTEN ALIGN FR L FENDER	New	1,500.00	650.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,200.00	1,040.00
Gross Labour Cost (S\$)			2,880.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >