

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23001135/ANP3E2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant:	TERRENCE NG TECK LENG	Policy No:	1800053988-04	
Date of Loss:	28/01/2023	Nature of Claim:	OD	Claim No: 4023370740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1912E	Engine No:	CWG069579
Make & Model:	AUDI S5 SPORTBACK, 3.0 (A)	Chassis No:	WAUZZZF56JA087254
Reg. Date:	15/05/2018 (Man. Year: 2018)	Odometer:	31228 km
Colour:	Grey		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$230,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,501.00	11,936.32	8,564.68	41.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,252.00	3,022.00	3,230.00	51.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,753.00	14,958.32	11,794.68	44.09
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	23,753.00	11,958.32	11,794.68	49.66
+ GST 8.00/8.00% (S\$)	1,900.24	956.67	943.57	49.66
Nett Amount (S\$)	25,653.24	12,914.99	12,738.25	49.66

INSPECTION

Date of Assignment:	03/02/2023		
Date Inspected:	02/02/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,313.00 FS	*2,650.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	452.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	42.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	269.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Cracked	92.00 FS	*72.96 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	873.00 FS	*698.00 FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	43.00 FS	*- FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	151.00 FS	*- FS
9	1		*CAUTION SIGN STICKER	Not Necessary	17.00 FS	*- FS
10	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	272.00 FS	*- FS
12	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
13	1		*HORN HIGH TONE - LH	Not Necessary	142.00 FS	*- FS
14	1		*HORN BRACKET - LH	Not Necessary	35.00 FS	*- FS
15	1		*FRONT FENDER - LH	Buckled	1,258.00 FS	*1,006.40 FS
16	1		*FRONT FENDER CLOSING ELEMENT - LH	Deformed	88.00 FS	*70.00 FS
17	1		*FRONT FENDER BRACKET - LH	Damaged	44.00 FS	*34.80 FS
18	6		*FRONT FENDER RIVET	Necessary	24.00 FS	*19.20 FS
19	1		*FRONT FENDER BRACE - LH	Not Necessary	140.00 FS	*- FS
20	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	Not Necessary	59.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - LH CENTER	Not Necessary	42.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	322.00 FS	*- FS
23	1		*FRONT WHEEL SPOILER	Torn	87.00 FS	*68.96 FS
24	1		*FRONT WHEEL SPOILER END PLATE - LH	Not Necessary	42.00 FS	*- FS
25	1		*FRONT WHEEL SPOILER STONE CHIP GUARD - LH	Not Necessary	60.00 FS	*- FS
26	1		*FRONT WHEEL SPOILER TRIM BRACKET - LH	Not Necessary	29.00 FS	*- FS
27	1		*FRONT FENDER CHROME TRIM - LH	Necessary	217.00 FS	*173.60 FS
28	1		*FRONT FENDER LEDGE COVER - LONG	Not Necessary	42.00 FS	*- FS
29	1		*FRONT FENDER LEDGE COVER - LH SHORT	Deformed	19.00 FS	*14.80 FS
30	1		*HEADLIGHT - LH	Cut	8,909.00 FS	*7,127.20 FS
31	1		*LIFT CYLINDER - LH	Not Necessary	230.00 FS	*- FS
32	1		*LIFT CYLINDER BRACKET - LH	Not Necessary	17.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - LH INNER	Not Necessary	38.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - LH OUTER	Not Necessary	25.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	25.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE - LH	Not Necessary	53.00 FS	*- FS
37	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	2,502.00 FS	*- FS
38	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
39	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
40	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	104.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,501.00 11,936.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,252.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >