

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001144/SNP3E2**Date:** 24/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00222462201
Claimant Vehicle No :	SMA2161X	Insured Vehicle No :	SJT732Y
Date of Loss:	31/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200845/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA2161X	Engine No:	L15B4031503
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11111505
Reg. Date:	26/04/2016 (Man. Year: 2015)	Odometer:	90312 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,702.48	2,966.48	6,736.00	69.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	1,340.00	2,350.00	63.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,392.48	4,306.48	9,086.00	67.84
Approved Total (Overridden) (S\$)		3,450.00		
Nett Amount (S\$)	13,392.48	3,450.00	9,942.48	74.24

INSPECTION

Date of Assignment:	03/02/2023	
Date Inspected:	03/02/2023	Inspected At: 4rensic Motors Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #01-50, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA2161X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	987.50 FL	*987.50 FL
2	1		*TAILGATE WINDSCREEN GLASS RH RUBBER SEAL }	Necessary	51.00 FL	*121.00 FL
3	1		*TAILGATE WINDSCREEN GLASS RH RUBBER SEAL }		51.00 FL	*- FL
4	1		*TAILGATE WINDSCREEN GLASS UPPER RUBBER SEAL }		51.00 FL	*- FL
5	1		*TAILGATE WINDSCREEN GLASS LOWER RUBBER SEAL }		51.00 FL	*- FL
6	1		*TAILGATE OUTER GARNISH	Not Necessary	256.80 FL	*- FL
7	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	80.00 FL	*- FL
8	1		*TAILGATE OUTER GARNISH EMBLEM	Not Necessary	58.00 FL	*- FL
9	3		*TAILGATE OUTER GARNISH EMBLEM CLIPS	Not Necessary	18.50 FL	*- FL
10	1		*TAILGATE REVERSE CAMERA	Not Necessary	1,035.00 FL	*- FL
11	1		*TAILGATE VEZEL EMBLEM	Necessary	58.70 FL	*58.70 FL
12	1		*TAILGATE RH LAMP ASSY	Not Necessary	487.60 FL	*- FL
13	1		*TAILGATE RH LAMP GASKET	Not Necessary	23.00 FL	*- FL
14	1		*REAR LH LAMP ASSY	Not Necessary	487.60 FL	*- FL
15	1		*REAR LH LAMP GASKET	Not Necessary	23.00 FL	*- FL
16	1		*TAILGATE PULL GARNISH HANDLE	Not Necessary	32.20 FL	*- FL
17	1		*TAILGATE INNER TRIM BOARD	Cracked	189.90 FL	*189.90 FL
18	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FL	*30.00 FL
19	1		*TAILGATE LOCK	Not Necessary	189.30 FL	*- FL
20	1		*TAILGATE LOCK CATCH	Not Necessary	33.00 FL	*- FL
21	1		*TAILGATE WEATHERSTRIP	Cut	223.40 FL	*190.00 FL
22	1		*TAILGATE OUTER HANDLE	Not Necessary	134.20 FL	*- FL
23	1		*REAR BUMPER	Broken	512.70 FL	*512.70 FL
24	1		*SET REAR BUMPER CLIPS	Not Necessary	80.00 FL	*- FL
25	1		*REAR BUMPER CENTRE GARNISH	Dented	288.00 FL	*288.00 FL
26	1		*REAR BUMPER RH REFLECTOR	Not Necessary	141.50 FL	*- FL
27	1		*REAR BUMPER LH REFLECTOR	Cracked	141.50 FL	*141.50 FL
28	1		*REAR BUMPER LOWER COVER	Not Necessary	250.00 FL	*- FL
29	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	28.90 FL	*- FL
30	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	28.90 FL	*- FL
31	1		*REAR BUMPER RH SIDE COVER	Not Necessary	196.00 FL	*- FL
32	1		*REAR BUMPER LH SIDE COVER	Not Necessary	196.00 FL	*- FL
33	1		*END PANEL	Dented	438.00 FL	*438.00 FL
34	1		*END PANEL INNER GARNISH	Cracked	98.30 FL	*98.30 FL
35	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	40.00 FL	*40.00 FL
36	1		*END PANEL ANTENNA SENSOR	Not Necessary	78.30 FL	*- FL
37	1		*END PANEL BUZZER SENSOR	Not Necessary	89.00 FL	*- FL
38	1		*RH TAILLAMP ASSY	Not Necessary	488.90 FL	*- FL
39	1		*RH TAILLAMP GASKET	Not Necessary	23.00 FL	*- FL
40	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	22.00 FL	*- FL
41	1		*RH TAILLAMP PANEL	Not Necessary	156.00 FL	*- FL
42	1		*LH TAILLAMP ASSY	Not Necessary	488.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*LH TAILLAMP GASKET	Not Necessary	23.00 FL	*- FL
44	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	22.00 FL	*- FL
45	1		*LH TAILLAMP PANEL	Not Necessary	156.00 FL	*- FL
46	1		*RH REAR FENDER ARCH MOULDING	Not Necessary	195.00 FL	*- FL
47	1		*SET RH REAR FENDER ARCH MOULDING CLIPS	Not Necessary	70.00 FL	*- FL
48	1		*RH REAR FENDER INNER TRIM BOARD	Not Necessary	311.00 FL	*- FL
49	1		*SET RH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	80.00 FL	*- FL
50	1		*LH REAR FENDER ARCH MOULDING	Cracked	195.00 FL	*195.00 FL
51	1		*SET LH REAR FENDER ARCH MOULDING CLIPS	Necessary	70.00 FL	*30.00 FL
52	1		*LH REAR FENDER INNER TRIM BOARD	Not Necessary	211.00 FL	*- FL
53	1		*SET LH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	80.00 FL	*- FL
54	1		*REAR FLOOR COMPARTMENT TOP COVER BOARD	Not Necessary	493.00 FL	*- FL
55	1		*REAR FLOOR COMPARTMENT SPONGE TRAY	Not Necessary	311.00 FL	*- FL
56	1		*EXHAUST SILENCER	Not Necessary	537.00 FL	*- FL
57	1		*EXHAUST SILENCER GASKET	Not Necessary	49.00 FL	*- FL
58	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
59	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
60	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*40.00 FS
61	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*180.00 FS
62	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*50.00 FS
63	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	50.00 FS	*- FS
64	1		*LH TAILLAMP PANEL JOINT SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,940.60	3,630.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,238.12	664.12
Total Parts (\$\$)	9,702.48	2,966.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK , REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/ WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	0.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	80.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	120.00	0.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	150.00	0.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	120.00	30.00
9	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARDS TO ASSIST REPAIR	New	320.00	0.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	0.00
Gross Labour Cost (S\$)			3,690.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >