

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/HSB23001146/Rvp3e2
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	15/02/2023
	ATTN: LOW GARN	ET	Code:	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SH 9645M	Veh. Inspected	FBQ 3109M
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04II9	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	03/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. S1000RR	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WB1052409DZ038901	Colour	BLACK
	Odometer	55167 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70Z R17	BRIDGESTONE	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	200/55Z R17	BRIDGESTONE	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUS BODY.	STAINED DAMAGES AT THE FRONT PORTION AND O/S		
5.	General Information			
	Accident Date	27/01/2023	Inspect Date / Time	06/02/2023 ( 11:50 AM )
	Survey held at	20 BUKIT BATOK CRESCENT #	01-19, 658080	
	Repairer PRIMERO RACING			
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			
	Depart Ref No. CC2/UCD22004446/Dup2c2			

Report Ref No. CS3/HSB23001146/Rvp3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser