



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23001147/Kvy3e2 Date: 06/03/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 5175J	Veh. Inspected	EX 39D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/01/23/5025	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	03/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HARRIER (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTEZB3GH30J000787	Colour	METALLIC SILVER
	Odometer	144381 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	MICHELIN	6 mm
	L/H Front Tyre	235/55 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/55 R18	MICHELIN	5 mm
	L/H Rear Tyre	235/55 R18	MICHELIN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	28/01/2023	Inspection Date	06/02/2023
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	