

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23001149/ATQY3M4**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001891387		
<b>Claimant Vehicle No :</b>	SJN4476S	<b>Insured Vehicle No :</b>	FBJ324P		
Date of Loss:	09/11/2022	Nature of Claim:	TP	Claim No:	292259

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJN4476S</b>	Engine No:	R18A1788637
Make & Model:	HONDA STREAM, 1.8 L RSZ (A)	Chassis No:	RN61079763
Reg. Date:	16/02/2009 (Man. Year: 2008)	Odometer:	218145 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,795.20	2,276.00	1,519.20	40.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	930.00	1,220.00	56.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,945.20</b>	<b>3,206.00</b>	<b>2,739.20</b>	<b>46.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,945.20</b>	<b>2,550.00</b>	<b>3,395.20</b>	<b>57.11</b>

**INSPECTION**

Date of Assignment:	03/02/2023		
Date Inspected:	06/02/2023	Inspected At:	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408700
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN4476S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FOG LAMP	Not Necessary	298.00 FL	*- FL
2	1		*BONNET	Dented	1,100.00 FL	*689.00 FL
3	1		*FRONT GRILLER	Cracked	426.00 FL	*268.00 FL
4	1		*FRONT GRILLER OUTER MOULDING	Cut	380.00 FL	*280.00 FL
5	1		*FRONT GRILLER RSZ PLATE	Necessary	120.00 FL	*45.00 FL
6	6		*FRONT GRILLER INNER CLIPS	Necessary	36.00 FL	*30.00 FL
7	1		*FRONT GRILLER EMBLEM	Necessary	98.00 FL	*48.00 FL
8	1		*N/S HEADLAMP	Cracked	788.00 FL	*685.00 FL
9	1		*FRONT BUMPER	Deformed	988.00 FL	*683.00 FL
10	1		*FRONT BUMPER LOWER GRILLER	Deformed	380.00 FL	*87.00 FL
11	10		*FRONT BUMPER INNER CLIPS	Necessary	50.00 FL	*30.00 FL
12	10		*BONNET INSULATOR CLIPS	Not Necessary	80.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,744.00	2,845.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	948.80	569.00
Total Parts (\$\$)	3,795.20	2,276.00

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUSTPROOF	New	150.00	30.00
2	TO DISMANTLE/RENEW ACCIDENT PORTION	New	1,000.00	500.00
3	TO SPRAY PAINT	New	1,000.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>2,150.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >