



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET		Ref: CS/HSB23001150/Aqp3m4 Date: 15/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDX 9033Y	Veh. Inspected	PC 1366H
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04IPI	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	03/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	KDH2220035418	Colour	SILVER
Odometer	550349 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	WANLI	6 mm
L/H Front Tyre	195 R15C	WANLI	6 mm
R/H Rear Tyre	195 R15C	WANLI	6 mm
L/H Rear Tyre	195 R15C	WANLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/02/2023	Inspection Date	06/02/2023
Survey held at	1 Kaki Bukit Ave 6, Autobay, #01-15 S 417883		
Repairer	AUTOMOBILE HUB ENTERPRISE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	